

SME7320A.

Honda Stream.

TP China.

Veron.

JHMRN684085205861.

Rear Number Plate	2 Nof per	30(SN) X
Rear Number Plate Holder		30(SN) X
Rear Bumper Distorted		683.40 ✓
Rear Bumper Clips per		30(SN) ✓
Rear Bumper Side Holder x 02	per	28.2 X 2 = 56.40 ✓
Rear Bumper Lower Brackett. x 02	Best	25.5 X 2 = 51 ✓
Rear Bumper Tow Cover	Deh	28.70 ✓
Reuse Sensor (4 pieces).	per	350(SN) 280(SN)
Rear End Panel	Dented	425.90 ✓
Rear End Panel Top Garnish.	curled	165.40 ✓
Rear End Panel Top Garnish Clips	per	20(SN) ✓
Rear End Panel Sealant.	per	60(SN) ✓
Rear End Panel Inner Member.	Dented	279.60 ✓
Tail Lamp x 02	LH curled	368.2 X 2 = 736.40 368.20

SME 7320A.

Tailgate	Distorted	903.	✓
Tailgate Lock	Dry d	183.70	✓
Tailgate Weatherstripe.	lt	116.90	✓
Tailgate Inner Trim Board	Authd	288.60	✓
Tailgate Inner Trim Board clips	in	30(SN)	✓
Tailgate Outer Garnish	MP	184.50	X
Tailgate Glass Moulding?		108	✓
Tailgate Glass Sealant.	MP	60(SN)	✓
Honda Logo.	XHE mee	35.40	X
Stream Emblem.	Mee	45.90	✓
Rear Fender Inner Trim Board	LT Authd	316.20	
Rear Fender Inner Trim Board clips.	MP	316.24 x 2 = 632.48	
Floor Panel Top Board	MP	277.30	X
Rear Exhaust Pipe.	MP	567.	X
Rear Exhaust Moulding.	MP	30.40	X

SME 7320A.

Panel Beating	1400 900
Spray Painting.	1200 800
Wiring.	50 30
To spray tuff coat.	150 60
To remove reverse sensor	100 50
To remove upholstery.	150 60
To transfer tailgate fittings.	150 80
To remove tailgate glass	180 120
To remove exhaust pipe.	150 X
To remove rear camera	400 50

List: 4020.90 Labour: 2150
Len 20%: 321672 Total: 5876.72
SN: 510 H/S: A7K
07 Dm/s.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
15/06/2021

