

Koh & Lim Motoring Services

Block 160 Sin Ming Drive #05-14 Sin Ming Autocity
Singapore 575722 HP 91004390/91254449 Fax 6484 1482
Email: kohlimmotoring@gmail.com

Invoice No :

M/s China Taiping Insurance (S) Pte Ltd	DATE	22.06.2021
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SLN 8251 Z
Singapore 079909	MAKE	Kia Cerato

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : GBF 969 A

Pc	Pcs	KNAFZ411MH720503	UNIT PRICE	AMOUNT
1	pcs	Front bumper		\$505.00
1	pcs	Front bumper right hand side retainer	✓ 36.00 ✓	✓ \$18.00 ✓
10	pcs	Front bumper clips	\$3.00	✓ \$30.00
1	pcs	Front bumper right side bracket		✓ \$22.00
1	pc	Front bumper fog lamp grille (right)		✓ \$25.00 ✓
				88.00
Spraying anti-rust coating onto new and affected panels.				\$60.00
Straightening, repairing, knocking onto vehicle front portion, dismantle & replace the above mentioned parts.				300.00
Labour for respray front bumper.				200.00
<div style="border: 1px solid blue; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				500.00
				588.00
				117.60
				470.40
Total				\$1,560.00

Susan Lim

Koh & Lim Motoring Services

Survey on 22/6/2021
1245
TGM in Lin

NO Resurvey required.
All external damages are light. Lin

Lump sum repair
Repair days 3
COR L/S 450.00