

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 01 Jun 2021

Preliminary Advice

Vehicle No	: SKE3006H	Accident Date	: 24/05/2021
Make	: AUDI Q7	Policy No.	:
Assignment Date	: 31/05/2021	Excess	: S\$500.00
Date of Inspection	: 28/05/2021	Est. Duration of Repair	: 4
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,292.00
Revised Amount	:S\$	8,288.00
Check Items (Estimated)	:S\$	2,041.00
Total	:S\$	10,329.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	205,000.00
COE / PARF Rebate	:S\$	82,207.00
Salvage Value	:S\$	
Margin for Repair	:S\$	122,793.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :