

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0453/2021/KS
DATE : 27-May-21
WIP : 28788

Xiao Chen.
7116.56.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/5/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN BENG WAH GEOFFREY
ADDRESS : 55 JALAN MENARONG
SINGAPORE 577462
TELEPHONE : HP +65 96827972
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800125499-02
VEHICLE NO : **SKE 3006 H**
MODEL CODE : Q7 2.0 TFSI QU
MODEL YEAR : 26/10/2018
ENGINE NO : CYR 069036
CHASSIS NO : WAUZZZ4M1JD060052
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-May-21
PLACE OF ACCIDENT : CORNER OF JLN KURAS AND JLN GELLENGGAN

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKE 3006 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	✓ ✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHT AND REAR WIPER ASSY.	S/N \$ 480.00	X
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	S/N \$ 200.00	X
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	600 ✓
7	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,700.00	1200 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
SUB TOTAL LABOUR CHARGES		\$ 10,412.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 3006 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER TOP <i>} Delivered</i>	1	\$ 1,362.00 ✓	1089.60
2	REAR BUMPER BOTTOM <i>} Delivered</i>	1	\$ 1,798.00 ✓	1438.40
3	REAR BUMPER FIXING PARTS <i>See</i>	1	\$ 208.00 ✕	
4	REAR BUMPER SPOILER <i>Cracked</i>	1	\$ 1,261.00 ✓	1008.80
5	REAR BUMPER SPOILER TRIM <i>Not in</i>	1	\$ 107.00 ✕	
6	REAR BUMPER REINFORCEMENT BEAM <i>Not in</i>	1	\$ 1,417.00 ? ✕	
7	REINFORCEMENT BEAM SEAL LH / RH <i>Not in</i>	2	\$ 28.00 ✕	
8	REAR BUMPER HOLDING STRAP <i>Not in</i>	1	\$ 182.00 ? ✕	
9	REAR BUMPER GUIDE SECTION - CENTER <i>Not in</i>	1	\$ 142.00 ? ✕	
10	REAR PARKING AID SENSOR <i>Not in</i>	1	TBC ✕	
11	REAR BUMPER TAILLIGHT - RH <i>Cracked</i>	1	\$ 359.00 ✓	286.80
12	REAR LID <i>Repair</i>	1	\$ 6,018.00 ✕	
13	REAR LID ATTACHMENT PARTS <i>Not in</i>	1	\$ 344.00 ✕	
14	REAR LID LOCK <i>} Not in</i>	1	\$ 248.00 ✕	
15	REAR LID LOCK COVER <i>} Not in</i>	1	\$ 13.00 ✕	
16	REAR LID PACKING ADHESIVE <i>} Not in</i>	1	\$ 19.00 ✕	
17	AUDI EMBLEM <i>} Not in</i>	1	\$ 138.00 ✓	110
18	"Q7" EMBLEM <i>} Not in</i>	1	\$ 99.00 ✓	79.04
19	"TFSI" EMBLEM <i>} Not in</i>	1	\$ 99.00 ✓	79.04
20	"QUATTRO" EMBLEM <i>Not in</i>	1	\$ 99.00 ✓	79.04
SUB TOTAL SPARE PARTS		:	\$ 13,941.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 3006 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR WINDSCREEN	1	\$ 1,174.00	X	
22	REAR WINDSCREEN PRIMER	1	\$ 20.00	X	
23	REAR LID SPOILER LH / RH	2	\$ 462.00	X	
24	REAR BUMPER FIXING PARTS	1	\$ 62.00	X	
25	REAR EXHAUST TAILPIPE TRIM RH <i>ut</i>	1	\$ 329.00	✓	262.80
26	REAR WHEEL ARCH COVER LH / RH <i>xlu</i>	1	\$ 392.00	✓	313.60
27	REAR WINDSCREEN SEALANT <i>xtm</i>	S/N	\$ 200.00	X	
28	SUNDRIES <i>Nec.</i>		\$ 300.00	?	17.44 ✓
TOTAL SPARE PARTS			\$ 16,880.00		
TOTAL LABOUR CHARGES			\$ 10,412.00		
GRAND TOTAL			\$ 27,292.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *28/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

ll.s.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT