

TP MS16.

Veron

SMP5108C 2011 Feb.

Porsche Panamera. 3605 cc

WPOZZZ972BL003081

Front Bumper	Dented	2409.50	✓
Front Bumper Clips	m	50	✓
Front Bumper Side Holder RH.	Dnd	78	✓
Front Bumper Sensor x 02	1 piece dnd	$312.7 \times 2 = 625.40$	312.70
Front Bumper Reinforcement	MP	945	X
Front Bumper Sponge	MP	320.40	X
Front Bumper Lamp RH.	Cracked	655.10	✓
Front Bumper Air Grille RH.	MP	187.60	X
Front Bumper Nozzle Pump RH.	MP	445.20	X
Headlamp RH	Cracked	2872.80	✓
Headlamp Lower Bracket RH.	Cracked	200.40	✓
Front RH Fender	Dented	1113.20	✓
Front RH Fender Inner Shield	MP	439.30	X
Front RH Fender Inner Shield Clips	MP	50	X
Front RH Fender Inner Bracket	Best	349.80	✓

SMP S108C.

Front RH Wheel Rim. ^{wt}

~~3122~~ 1200(SN)

Front RH lower Arm.

1872.50x

Front RH Knuckle Arm.

2212.50x

Front RH Shock Absorber.

1733.60x

Front RH Wheel Hub c/w Bearings.

855.50 x

8141.60 S-N: 1200
7327.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Panel Beating

Spray Painting.

Wiring.

1400

To Spray full coat.

To perform diagnostic test

To perform wheel alignment.

To dismantle front undercarriage.

To remove front bumper sensor

total 9927.44

H/S: 7.9K 84 Days

~~1000~~ 600.
~~1000~~ 500

~~1000~~ 30

~~1200~~ 30

~~2000~~ 100

~~1500~~ 80.

380 x

150 60

23,738.30