

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

Steve (LKK) w/L AL
1/6/21, 9.00am L/SBy AL sy
6 dly r

QT21/PC4064J/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC4064J

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front RH rear view mirror assy / CRA/CUT	1	1,450.00	1200 / 1,450.00
2.	Front panel / DO	1	4,200.00	3400 / 4,200.00
3.	Front RH headlamp assy / CUT	1	1,350.00	1100 / 1,350.00
4.	Front bumper / DO	1	1,650.00	1300 / 1,650.00
5.	RH linkage (Rmt dip) / DO	1	1,480.00	1090 / 1,480.00
6.	ERP / NEC	1	26.00	22 / 26.00
7.	Sealant / NEC	10	40.00	400.00 ✓
8.	Check wiring / NEC	1	30.00	30.00 ✓
9.	Labour to remove & refit front windscreen	1	1,000.00 ✓	1,000.00
10.	Labour charges	1	1299 1,500.00	1,500.00
11.	Spray painting	1	800 1,000.00	1,000.00
SUB-TOTAL				S\$14,086.00

- Price b4 7% gst

Thank you.
Yours faithfully,

P- 8000
-10%
7200

M-452 L-3000
=10,652
L/S-8521.60
=8500