

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

TPA16
Cecilina.

Vehicle Number : SMJ3314T
Vehicle Model : MER. BENZ CLA180
Accident Date : 14.05.2021
Original Reg Date : 28.02.2019

Date : 27.05.2021
Chassis : WDD1173422N748419
TP Ins. AIG

ESTIMATE

1	1 pc	Front Bumper <i>Rehd</i>		1,526.90	✓
2	1 pc	Front Bumper Side Retainers <i>Left Nec</i>		98.70	✓
3	1 pc	Front Bumper Sponge <i>the m</i>		198.50	+
4	1 pc	Front Bumper foglamp cover <i>the m</i>		98.60	+
5	2 pc	Front Bumper sensor <i>Damaged</i>	256.30	512.60	256.30
6	2 pc	Front Bumper sensor holder <i>the m</i>	48.60	97.20	+
7	1 pc	Front headlamp <i>lit</i>		2,780.20	✓
8	1 pc	Front Fender LH <i>Dented</i>		987.60	746.
9	1 pc	Front Fender Inner Shield LH <i>Dented</i>		198.50	✓
10	1 pc	Side mirror LH assy <i>new</i>		896.30	+
11	1 pc	Side skirt <i>Regr</i>		987.50	+
12	1 pc	Front Lower Arm LH <i>Best</i>		547.30	✓
13	1 pc	Front Knuckle Arm LH <i>Rehd</i>		835.60	✓
14	1 pc	Front Wheel Bearing LH <i>Rehd</i>		425.70	✓
15	1 pc	Front steering rack <i>new</i>		2,285.90	+
16	1 pc	Front Anti Roll Bar Link LH <i>Recover</i>		98.50	x
17	1 pc	Front Anti Roll Bar		798.30	x
18	1 pc	Front Drive Shaft LH <i>new</i>		1,857.00	x
19	1 pc	Front Sport Rim LH <i>lit</i>		987.60	✓
20	1 pc	Front Door Lh <i>Regr</i>		2,085.90	+
21	1 pc	Front Door inner trim Lh <i>new</i>		725.80	x
22	1 pc	Rear Door Lh <i>the m</i>		1,986.30	+
23	1 pc	Front Sport Rim LH <i>the m</i>		987.40	+

22,003.90

Less 10% 2,200.39

19,803.51

8402.80

7562.52

Special Nett

1	1 pc	Front Sport Rim Tyre LH <i>neu</i>	280.00	+
2	1 set	Front Fender Inner Shield Clips <i>neu</i>	30.00	✓
3	1 set	Front headlamp clips <i>neu</i>	30.00	+
4	1 set	Front bumper clips <i>neu</i>	30.00	✓
5	1 set	Side skirt clips <i>neu</i>	30.00	+

60

Labour charge

Panel Beating	1,800.00	600
Spray painting	1,600.00	750
Check Wiring on headlamp and focussing	120.00	30
To remove and install sensor	150.00	60
Anti rust	180.00	50
Remove and install front undercarriage.	180.00	✓
To transfer front door mechanism	180.00	+
To perform computerize wheel alignment.	120.00	80

1750

total \$ 24,533.51

Admin L
L/s 28/05/21.
0.5 Pays.

total: 9372.512
L/s: 7.51c

751c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044
TEL: 67466686
H/P: 85153676

Work Order: R003440
License: SMJ3314T
Date: 27.5.21 17:26

Mercedes-Benz : 117 (CLA Class 2013-19) : with Code 485 (C/X)

Front : Left

Actual	Before	Specified Range
1°15'	1°15'	-1°17' -0°37'
0°00'	0°00'	
0°36'	0°36'	0°02' 0°12'
-0°45'	-0°45'	
0°30'	0°30'	
		-1°24' -0°24'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°53'	-0°53'	-1°17' -0°37'
0°00'	0°00'	
0°23'	0°23'	0°02' 0°12'
1°23'	1°23'	
0°30'	0°30'	
		-1°24' -0°24'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°08'	2°08'	-0°24' 0°24'
0°00'	0°00'	-0°30' 0°30'
-2°08'	-2°08'	
0°59'	0°59'	0°04' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°08'	-1°08'	
0°00'	0°00'	-0°04' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°05'	-1°05'	
0°00'	0°00'	-0°04' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°03'	-0°03'	-0°30' 0°30'
0°00'	0°00'	0°00' 0°14'
0°00'	0°00'	-0°08' 0°08'