



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Qty	Parts Description		Estimated Parts Price
1	1	Front bumper assy	1380	\$ 1,590.00 <i>de</i>
2	1	Front bumper bracket left	76	\$ 295.00 <i>de</i>
3	1	Front bumper side metal piece left		\$ 125.00 <i>by</i>
4	1	Front bumper reinforcement	300	\$ 548.00 <i>by</i>
5	1	Inside bumper sponge	168	\$ 195.00 <i>de</i>
6	1	Bumper lower lip		\$ 295.00 <i>de</i>
7	1	Front bumper lower grille	135	\$ 285.00 <i>de</i>
8	1	Front bumper lower silver chrome both side		\$ 205.00 <i>na</i>
9	1	Front bumper tow cover		\$ 85.00 <i>X</i>
10	2	Fog lamp cover left		\$ 280.00 <i>X</i>
11	1	Fog lamp inner base chrome		\$ 150.00 <i>X</i>
12	2	Fog lamp silver lining		\$ 190.00 <i>X</i>
13	1	Fog lamp		\$ 285.00 <i>X</i>
14	1	Front grille assy	412	\$ 565.00 <i>af</i>
15	1	Front grill base	155	\$ 268.00 <i>am</i>
16	1	Front grill top silver lining		\$ 135.00 <i>X na</i>
17	1	Front emblem		\$ 98.00 <i>na</i>
18	1	Front top cover trim		\$ 225.00 <i>X na</i>
19	1	Front bonnet assy		\$ 2,250.00 <i>XR</i>
20	1	Front bonnet lock		\$ 185.00 <i>X na</i>
21	1	Sensor line cable		\$ 296.00 <i>X na</i>
22	1	Front support panel assy		\$ 348.00 <i>R</i>
23	1	Lower end carrier cover	265	\$ 323.00 <i>de</i>
24	1	Front right headlamp		\$ 1,590.00 <i>X na</i>
25	1	Front left headlamp	999	\$ 1,590.00 <i>cu</i>
26	1	Front right headlamp lower bracket		\$ 205.00 <i>X</i>
27	1	Front left headlamp lower bracket		\$ 205.00 <i>X</i>
28	1	Front right lamp control unit		\$ 650.00 <i>X</i>
29	1	Intercooler	750	\$ 1,415.00 <i>de</i>
30	1	Inercooler frame trim		\$ 293.00 <i>X na</i>
31	2	Inintercooler cover		\$ 90.00 <i>de</i>
32	1	Condenser	955	\$ 1,452.00 <i>de</i>
33	2	Condenser frame support		\$ 500.00 <i>X</i>
34	1	Fanmotor		\$ 965.00 <i>X</i>
35	2	Water pump hose		\$ 275.20 <i>X</i>
36	1	Radiator		\$ 932.00 <i>X</i>
37	1	Radiator grille		\$ 850.00 <i>X</i>

Sub-total

6408

\$ 20,233.20

10% - 5767.20



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Qty	Parts Description	Estimated Parts Price	
<u>Special Nett Items</u>				
1	10	Front bumper clips	\$	80.00 3 one ✓
2	6	Front bumper lower cover clips	\$	40.00 X ✓
3	8	Front fender clips	\$	40.00 X } un
4	6	Insulator clips	\$	30.00 X }
5	6	Bonnet seal clips	\$	50.00 X }
6	2	Sensor /distance sensor	\$	600.00 un / 400
7	8	Front support panel garnish clips	\$	30.00 X un
8	1	Front no plate with cashing	\$	80.00 4567 ✓
9	1	License plate holder	\$	135.00 de ✓
10	1	Sealant for front end panel	\$	60.00 X } un
11	1	Sealant for front side panel	\$	60.00 X }
<u>Special Nett Items</u>			\$	1,205.00
Total parts			\$	21,438.20 610



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, body main frame affected	\$ 2,500.00 400.
2	To putty and spray painting front portion.	\$ 2,000.00 200400
3	To check wiring and focus front headlamp.	\$ 80.00 30
4	To apply anti rust proofing to front affected area.	\$ 200.00 X
5	To remove and install front undercarriage parts.	\$ 150.00 X
6	To balance front right wheel.	\$ 80.00 X
7	To conduct wheel alignment.	\$ 120.00 X
8	To remove and install front bonnet lock mechanism assy.	\$ 100.00 X
9	To remove and install bumper sensor.	\$ 80.00 30
10	To conduct chassis alignment.	\$ 350.00 X un
11	To remove and install condensor and check leakage	\$ 150.00 100.
12	To remove and install radiator and check leakage	\$ 150.00 X un
13	To remove and install intercooler and monitoer performance	\$ 150.00 60.
14	To remove and install horn and check horn wiring	\$ 80.00 X un
15	To remove and install compressor and monitor performance	\$ 150.00 X un.
Total labour :		\$ 6,340.00 1020

Total Part 67,348.50
Total labour : 6,340.00
Total repair cost : 73,688.50

Tanpin 17495749
'WP' 4/s Resurvey after repair
1/6/21
tanpin@Mando.com.
4 days

5767.20
610
1020
7397.20
4/5 5900
4 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: