

Parts

- 1 Back Door Wiring Harness ? Xsu
- 2 Wire, Joint, Trunk Lid ? Xsu
- 3 Rear Windshield Heating Small Wire Xan
- 4 Rear Windshield Heating Negative Small Wire Xan
- 5 Middle Guide Rail Assy, Door, RL ? cr
- 6 Hinge Assy, Trunk Lid ? bt
- 7 Fixed Component, Guiding Mechanism, Trunk Lid ? Ne
- 8 Active Component, Guiding Mechanism, Trunk Lid ? Ne
- 9 Gas Spring Body, Left, Trunk Lid ? cut
- 10 Gas Spring Body, Right, Trunk Lid ? cut
- 11 Mounting Support, Buffer Block, Trunk Lid ne
- 12 Side Buffer Block, Trunk Lid ne
- 13 Lock Ring Assy, Trunk Lid ne
- 14 Lock Cover, Trunk Lid ? cr
- 15 Lock Assy, Back Door ? Jan
- 16 Wiper Motor, Rear ? bt
- 17 Wiper Arm & Wiper Blade Assy, Rear ? cr
- 18 Rear Wiper Shaft Cover de
- 19 Waterproof Cover ? ne
- 20 Weatherstrip, Back Door Frame ne
- 21 Glass, Rear Door bro
- 22 Rear Wall Panel Assy ? Xsu
- 23 Side Body Panel Assy, R repair
- 24 Side Body Panel Assy, L bu
- 25 Reinforcing Plate, Rear Wall Plate Bt
- 26 Door Assy bt
- 27 Left Shield Assy, Back Door ? Xan
- 28 Upper Shield Assy, Back Door ? Xan
- 29 Right Shield Assy, Back Door ? Xan
- 30 Lower Shield Assy, Back Door ? Xan
- 31 Pedal, Rear Rail ? ne
- 32 Back Door Lock Cover Board, Service Port ? cut
- 33 Rear Side Pedal Assy ? Xan
- 34 Auxiliary Handle, Trunk ne
- 35 Interior Shield Assy, Back Door scar
- 36 Light Garnish Assy, Rear License Plate ? cr
- 37 "T3" Mark Assy ne
- 38 Front Mounting Bracket Assy, Rear Bumper, L ? ne
- 39 Left Mounting Bracket II Assy, Rear Bumper ? ne
- 40 Rear Bumper Assy, White cr
- 41 Front Mounting Bracket Assy, Rear Bumper, R ne
- 42 Right Mounting Bracket II Assy, Rear Bumper ne
- 43 Combination Lamp Assy, RL br
- 44 License Plate Light, Left ? cr
- 45 License Plate Light, Right ? cr

Qty Total Price (\$\$)

1	Factory Backorder	
1	\$	159.52
1	\$	11.56
1	\$	10.84
1	\$	248.66
2	Factory Backorder	185.70
1	\$	9.56
1	\$	5.82
1	\$	60.10
1	\$	54.84
1	\$	12.72
1	\$	2.60
1	\$	11.04
1	\$	10.72
1	\$	119.48
1	\$	173.76
1	\$	54.42
1	\$	2.62
1	\$	2.04
1	\$	53.96
1	\$	104.20
1	Factory Backorder	
1	\$	8,106.84
1	Factory Backorder	8408.84 8106.84
1	Factory Backorder	354.80
1	\$	9,933.60
1	\$	26.26
1	\$	45.10
1	\$	28.08
1	\$	198.80
1	\$	11.62
1	Factory Backorder	99.48
1	Factory Backorder	
1	\$	3.76
1	\$	71.84
1	\$	146.52
1	\$	11.36
1	\$	27.68
1	\$	17.02
1	\$	460.34
1	\$	23.62
1	\$	17.52
1	\$	161.20
1	\$	5.58
1	\$	6.48

35.00 EA
125.00 EA
82.05 EA
9.58 EA
5.82 EA
0.10 EA
0.04 EA
0.04 EA
0.04 EA
0.04 EA

- 46 Rear Logo Assy, LED *nm / /*
- 47 High Mounted Brake Lamp *? can*
- 48 Trim Panel Assy, Guide Rail, L-White *? x m* ✓ **NEC**
- 49 Reverse Camera Set. *? x m*
- 50 Rear Reg Plate *nm*
- 51 Windscreen Sealant Kit. *nm /*

1	\$	54.98
1	\$	35.14
1	\$	79.04
1	\$	350.00
1	\$	35.00
1	\$	125.00 ✓

TOTAL:	\$	21,090.84	\$	8,880.00
		Total Labour	:	\$ 8,880.00
		Total Parts	:	\$ 21,090.84
			:	\$ 29,970.84
		Plus 7% GST	:	\$ 2,097.96
		Grand Total	:	\$ 32,068.80

Should this repair job require any additional parts, we will inform you and bill you accordingly.
Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation.

[Signature]
JULIUS TAN

Workshop Department

Signature & Company stamp

[Signature]

Hp 90010068

22 days

P/P

31/05/21 @ 1530

Resuy before part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Motor Claim Department
Lonpac insurance Bhd
300, Beach Road,
Singapore 199555

customer_sg@lonpac.com

31 May 2021

Dear Sir / Madam

RE: BYD model T3, Vehicle Reg.No:GBL2140D,Chassis No.LC0CE4DB2L0011691

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) Labour Description

Part Cost

Labour Cost

- 1 Remove, install & renew to facilitate repairs :-
 - Rear fender inner plastic panels .
 - Rear wiper motor, machanism, arm & harness.
 - Rear reg plate lamp assy & harness .
 - Third brake lamp assy .
 - Left tail lamp & harness.
 - Parking sensor & harness.
- 2 Remove & renew rear bumper.
- 3 Remove & renew rear left fender include cut & arc welding.
- 4 Remove & renew Rh triple layer "D" pillar include cut & arc welding.
- 5 Remove & renew end panel include cut & arc welding.
- 6 Remove,renew & align tail gate .
- 7 Install tailgate screen.
- 8 Water test on all repaired area .
- 9 Disconnect, connect & configure EV battery to facilitate arc welding.
- 10 Respray premier,paint body colour & blend :
 - a Outer Lh rear fender
 - b Inner Lh rear fender
 - c Outer Rh rear fender.
 - d Inner Rh rear fender.
 - e Outer Tail gate .
 - f Inner Tail gate
 - g Rear bumper.

7715

	\$	450.00
		405
	\$	270
		300.00
2520	\$	2,800.00
850	\$	980.00
320	\$	450.00
280	\$	350.00
250	\$	350.00
120	\$	200.00
1000	\$	1,200.00
1700	\$	1,800.00