



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /YEO LENG QUEE (YANG LONGGUI) Reg No/Reg Date SMM6283M*KC17/ 08/07/201 Date In/Mileage 31/05/2021/ 0 Chassis No KNAF3416MK5046337 Engine No G4FGKH740819 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/05/2021/ 16:14	QUC	442 / Cocolu	34027		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT SUPPORT PANEL REPAIR ON FRT FENDER (LH) & RH & BONNET				1 X 400			400 1200.00
E PNT98000 SPRAY PAINT WORK ON FRT, BUMPER, FRT, LH FENDER, BONNET & AFFECTED AREAS				3 X 350			1050 1400.00
E PNT88000 TO REMOVE AND INSTALL FRT PARKING ASSIST SENSOR							80.00
M SUNDRY TO PERFORM RUST PREVENTION							80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME / CUT							50.00
M SUNDRY SUNDRIES							30 50.00
M COVER-FR BUMPER / GR				1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / CUT (BLACK)				1.00	485.00	20.00	388.00
M GRILLE ASSY-RADIATOR / X 1/4				1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE / GR				1.00	38.00	20.00	30.40
M COVER-FR BUMPER FOG LAMP, RH / GR CUT				1.00	15.00	20.00	12.00
M MOULDING-FRONT BUMPER, RH / GR				1.00	216.00	20.00	172.80
M ABSORBER-FRONT BUMPER ENERGY / GR				1.00	84.00	20.00	67.20
M BEAM COMPLETE-FR BUMPER / BT				1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE / X 1/4				1.00	675.00	20.00	540.00
M ORNAMENT-KIA NO.115 / REC				1.00	32.00	20.00	25.60
M LAMP ASSY-HEAD, RH / CAT				1.00	2210.00	20.00	1768.00
M LAMP ASSY-SIDE REPEATER, RH / CUT				1.00	143.00	20.00	114.40
M STIFFNER-FR BPR LWR / X 1/4				1.00	114.00	20.00	91.20

# Estimate

Sten (LKK)  
31/5/21, 4:30pm  
OD- N1 AL  
Exercis - ?

Estimate

Steer (CLKK)

31/5/21, 4:30pm

OD-NM AL

EXPIRY - ?

Confirm &amp; accepted by parts hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

P/P, M GEL Sy  
4 dys

Nett 7,386.00  
7% GST on 7386.00 517.02  
Total Payable 7,903.02

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.