

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Ho Yong Cheng

Accident Date : 21-May-21

Vehicle No : FBQ1463C

Honda Supra
Vehicle Model : GTR150
Manual

Accident involving SJC1080C and FBQ1463C on 21 May 2021

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>my</i>	\$	28.00	<i>20</i>
1	Sticker (1 set) <i>nel</i>	\$	95.00	<i>✓</i>
1	Rear tyre <i>11</i>	\$	130.00	<i>X</i>
1	Rear box <i>cu</i>	\$	420.00	<i>20</i>
1	Rear box bracket <i>n</i>	\$	120.00	<i>X</i>
		\$	793.00	

S/No. Labour

1	To provide towing service (LOD)	\$	50.00	<i>✓</i>
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00	<i>X</i>
3	To repair body frame	\$ <i>11</i>	280.00	<i>X</i>
4	To provide labour	\$ <i>250</i>	400.00	
		\$	810.00	

Grand Total

\$ 5,029.30

Singapore Dollars: Five Thousand Twenty-Nine and Cents: Thirty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1322
102
P-1189-80
S.N-315
L-300
1804-8