

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AXA

Name : Ho Yong Cheng

Accident Date : 21-May-21

Vehicle No : FBQ1463C

Honda Supra
Vehicle Model : GTR150
Manual

Accident involving SJC1080C and FBQ1463C on 21 May 2021

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Handle bar 11	\$ 88.00 X
1	Handle bar end 11	\$ 32.00 X
1	Hand grip (1 set) 11	\$ 55.00 X
2	Side mirror - R/L/H 0/5 cur	\$ 110.00 11
1	Front signal - L/H 11	\$ 70.00 X
1	Front signal lower garnish 0/5 cur	\$ 95.00
1	Brake lever 512	\$ 52.00
1	Fairing assy (1 set) cur	\$ 550.00
1	Front footrest bracket - R/H seat	\$ 65.00
1	Front footrest rubber - R/H 70.11	\$ 35.00
1	Brake pedal - R/H 11	\$ 42.00 X
1	Rear footrest - R/H cur	\$ 40.00
1	Rear footrest bracket 11	\$ 78.00 X
1	Exhaust assy 11	\$ 485.00 X
1	Exhaust protector cur	\$ 75.00
1	Exhaust end cover cur	\$ 45.00
1	Rear fender 520	\$ 185.00
1	Rear taillamp 11	\$ 215.00 X
1	Rear number plate lamp cover cur	\$ 150.00 X
1	Rear number plate lamp 220	\$ 125.00
1	Rear absorber 11	\$ 350.00 X
1	Rear wheel rim 11	\$ 220.00 X
1	Rear rim shaft 11	\$ 60.00 X
1	Rear rim bearing 11	\$ 45.00 X
1	Rear brake disc 11	\$ 160.00 X
1	Swing arm 11	\$ 380.00 X
		\$ 3,807.00
		Less 10%
		\$ 380.70
		\$ 3,426.30

not actual

21/5/21

H/S

Page 1 of 2

H. J. S.
Chapman & Co.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Ho Yong Cheng

Accident Date : 21-May-21

Vehicle No : FBQ1463C

Honda Supra
Vehicle Model : GTR150
Manual

Accident involving SJC1080C and FBQ1463C on 21 May 2021

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>ms</i>	\$	28.00	<i>20</i>
1	Sticker (1 set) <i>nel</i>	\$	95.00	<i>—</i>
1	Rear tyre <i>11</i>	\$	130.00	<i>X</i>
1	Rear box <i>un</i>	\$	420.00	<i>200</i>
1	Rear box bracket <i>n</i>	\$	120.00	<i>X</i>
		\$	793.00	

S/No. Labour

1	To provide towing service (LOD)	\$	50.00	<i>✓</i>
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00	<i>X</i>
3	To repair body frame	\$ <i>11</i>	280.00	<i>X</i>
4	To provide labour	\$ <i>250</i>	400.00	
		\$	810.00	

Grand Total

\$ 5,029.30

Singapore Dollars: Five Thousand Twenty-Nine and Cents: Thirty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: