

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006275/BPA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100424489
Claimant Vehicle No :	SMN2626D	Insured Vehicle No :	SKV68J
Date of Loss:	22/12/2020	Nature of Claim:	TP
		Claim No:	0356584187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN2626D	Engine No:	27492030227974
Make & Model:	MERCEDES-BENZ C200, 2.0 AMG (A)	Chassis No:	WDD2050422F055581
Reg. Date:	12/12/2014 (Man. Year: 2014)	Odometer:	73440 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,492.22	3,400.07	4,092.15	54.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	590.00	1,510.00	71.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,592.22	3,990.07	5,602.15	58.40
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,592.22	3,200.00	6,392.22	66.64
+ GST 7.00/7.00% (S\$)	671.46	224.00	447.46	66.64
Nett Amount (S\$)	10,263.68	3,424.00	6,839.68	66.64
+ Car Rental (4.0 x S\$160.00/day + 7.00% GST) (S\$)		684.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,116.25		
Global Sum Settlement (S\$)		4,110.00		

INSPECTION

Date of Assignment:	31/05/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	31/05/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	3.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,854.05 FL	*1,080.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	171.90 FL	*84.00 FL
3	1		*FRONT BUMPER INNER SPONGE	Broken	178.93 FL	*70.50 FL
4	1		*FRONT BUMPER LOWER CHROME MOULDING	Broken	310.48 FL	*165.00 FL
5	1		*FRONT BUMPER LISENCE PLATE	Repeated	148.23 FL	*- FL
6	1		*FRONT BUMPER PARKING SENSOR	N/S Scratched	369.28 FL	*138.00 FL
7	1		*FRONT BUMPER FOG LAMP GARNISH	Broken	74.55 FL	*74.55 FL
8	1		*FRONT BUMPER FOG LAMP GARNISH BASE	Broken	70.25 FL	*70.25 FL
9	1		*FRONT GRILLE ASSY	Broken	722.57 FL	*220.00 FL
10	1		*FRONT GRILLE LOGO	Cut	140.99 FL	*65.00 FL
11	1		*FRONT GRILLE BASE	Broken	140.90 FL	*127.00 FL
12	1		*HEADLAMP (LH)	Cut	3,389.18 FL	*1,628.00 FL
13	1		*HEADLAMP LOWER BRACKET	No such part	375.60 FL	*- FL
14	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
15	1		*FRONT BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
16	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
17	1		*FRONT GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
18	1		*FRONT NUMBER PLATE W/CASING	Cut	80.00 FS	*50.00 FS
					Sub Total (S\$)	8,286.91 3,772.30
					- List Item Discount on L Items 10.00/10.00% (S\$)	794.69 372.23
					Total Parts (S\$)	7,492.22 3,400.07

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT BUMPER PARKING SENSOR	New	100.00	60.00
2	DIGNOSTIC RESET FAULT CODE	New	300.00	0.00
3	CHECK WIRING	New	100.00	30.00
4	UPHOLSTERY	New	200.00	0.00
5	PANEL BEATING	New	600.00	300.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	600.00	200.00
Gross Labour Cost (\$\$)			2,100.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >