

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

31-May-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1240 B

1 pc	Bootlid CRDI	\$	27.00	ne
1 pc	Bootlid emblem	\$	29.00	ne
1 pc	Rear bumper	\$	696.00	df
1 pc	Rear bumper lower cover	\$	206.00	th
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	?
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	x
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00	\$	92.00	?
		\$	2,009.00	
		Less 10%	\$	200.90
			\$	1,808.10

### S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear bumper top protector
1 set	Bootlid stickers

Sundry

Towing Fee

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc

To putty and spray painting on rear bumper, end panel, bootlid lower garnish

To apply rustproofing on the repaired and replaced panels.

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	48.00	30
\$	280.00	200 nm
\$	80.00	50 ne
\$	100.00	
\$	50.00	x
\$	50.00	2.50 ne
\$	120.00	30.
\$	180.00	x
\$	750.00	300
\$	600.00	400
\$	80.00	x
\$	4,146.10	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Tanphu  
97495744  
WP 31/5/21  
0530  
4/5 Resurvey  
updo  
tanphu 11/6/21  
03 days