



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0460/2021/TF
DATE : 29-May-21
WIP : 29181

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

5 days exclude 1 Sunday - ok

Johnny Boo 16 Jul 21

OWNER'S NAME : SMP 2044 Y
ADDRESS : 80 LORONG K TELOK KURAU
#02-03
SINGAPORE 425710
TELEPHONE : HP +65 88281313
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900162090
VEHICLE NO : **SMP 2044 Y**
MODEL CODE : A3 SPORTSBACK 1.0 TFSI
MODEL YEAR : 9/16/2019
ENGINE NO : CHZ C35215
CHASSIS NO : WAUZZZ8V5LA002954
MILEAGE : 17845KM
DATE IN : 28-May-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-May-21
PLACE OF ACCIDENT : AIRPORT RD LEADING TO KPE TUNNEL

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 2044 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00	\$ 750.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$	3,000.00	\$ 1,750.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,552.00	\$ 3,252.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 2044 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,070.00	
2	REAR BUMPER ADAPTER - LH	1	\$ 38.00	
3	REAR BUMPER GUIDE SECTION - LH	1	\$ 67.00	
4	REAR DOOR - LH	1	\$ 2,767.00	
5	REAR DOOR OUTER SEAL - LH	1	\$ 161.00	
6	BONDING AGENT	1	\$ 49.00	
7	CLEANING SOLUTION	1	\$ 68.00	
8	APPLICATOR	1	\$ 8.00	
9	REAR DOOR CATCH - LH	1	\$ 94.00	
10	REAR WHEEL HOUSING LINER - LH	1	\$ 240.00	
11	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 57.00	
12	REAR TYRE RIM - LH	1	\$ 1,166.00	
13	SUNDRIES	1	\$ 250.00	
TOTAL SPARE PARTS			\$ 7,035.00	\$ -
TOTAL LABOUR CHARGES			\$ 6,552.00	\$ 3,252.00
GRAND TOTAL			\$ 13,587.00	\$ 3,252.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT