

1 of 2 ?	100%	Find Next
----------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref: CS3/LPC21006283/T1t3	
300 BEACH ROAD		Date: 01/06/2021	
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBC 561H	Veh. Inspected	SKG 1543B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	gerald	Assign Date	01/06/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/05/2021	Inspection Date	01/06/2021
Survey held at	333 AUTO GARAGE PTE LTD 15 KAKI BUKIT ROAD 4, #01-36, BARTLEY BIZ CENTRE, SINGAPORE 417808		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			