



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLR9283D

Tan Chen Siang, Nicodemus Hida

6 Sinaran Drive
#10-14 Soleil @ Sinaran
Singapore 307468

Mobile: +6597267897

Vehicle & Document Information

WIP No **50165**
Reg No/Reg Date **SLR9283D / 11/12/2017**
Date In/Mileage **0**
Chassis No **WDD2053402F636018**
Engine No **27491031212445**
Make/Model **MB/MB C 180 COUPE (C205)**
Colour/Trim **029 996 DesignoHyac/ 041 105 LeatherS.Be**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	27/05/2021/ 09:14	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN					
POLICY NO/ACC DATE : GA419688 // 23-05-2021					
DRIVE IN: 25-05-2021 // TP CAR NO: SG51596 (SMRT)					
DATE IN/DATE SURVEY:					
BY/AUTHORIZED ON :					
A BPILAB				0.10	380.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					
S BPNSUB					60.00
SUPPLY & TRANSFER 1PC FRONT LEFT RIM					
PURCHASE ORDER NO:					
A BPILAB					540.00
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT					
A BPILAB					1440.00
REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.					
A BPIRES					720.00
RESPRAY FRONT BUMPER					
M FRT BUMPER	1.00	1620.84	00.00		1620.84
M LH/F BUMPER BRACKET	1.00	12.88	00.00		12.88
M LH/F BASIC MOUNTING FOR BUMPER	1.00	85.57	00.00		85.57
M LH/F OUTER PARKING SENSOR	1.00	182.48	00.00		182.48
M LH/F PARKING SENSOR SEAL	1.00	6.35	00.00		6.35

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 5,048.12
7% GST on 5048.12 353.37

Total Payable 5,401.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg