



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21005271/Gqf3e2-1	
			Date: 14/06/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLB 608U	Veh. Inspected	SMX 8006B
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/21/21/VP05/024504	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	01/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH 1.8X	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	ZWR800436226	Colour	BLACK
	Odometer	15639 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/04/2021	Inspection Date	29/04/2021
	Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	