



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/KT/6217/8006/TP/04.21
Date : 02 May 2021

To: Skyway Motor Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop : Apex Motoring
Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment : 29 April 2021
Date of Accident : 27 April 2021
Date of Inspection : 29 April 2021

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SMX 8006B	Chassis Frame No.	: ZWR800436226
Make / Model	: Toyota Noah Hybrid 7-Seater 1.8X CVT	Engine No. (Logcard)	: 2ZR0F34408
Year of Manufacture/Reg	: 2020	Odometer Reading	: 15,639 KM
Colour	: Black		
Class / Type	: MPV		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Excellent
Paintwork : Excellent
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	GOODYEAR 195 / 65 R15	8 mm
Front R	GOODYEAR 195 / 65 R15	8 mm
Rear L	GOODYEAR 195 / 65 R15	8 mm
Rear R	GOODYEAR 195 / 65 R15	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



K A A S
kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m


Our Reference
Vehicle Number

: KAAS/KT/6217/8006/TP/04.21
: SMX 8006B

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	rear bumper	deformed	\$ 1,088.44	\$ 1,088.44
2	1 pc	rear bumper r/h side retainer	necessary	\$ 110.35	\$ 110.35
3	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
4	1 pc	tailgate	dented	\$ 1,806.95	repair
				\$ 3,040.74	\$ 1,233.79
		Less 25%			\$ 308.45
				\$ 3,040.74	\$ 925.34
Sub - Total				\$ 3,040.74	\$ 925.34

KR
KNN
KNN



Our Reference : KAAS/KT/6217/8006/TP/04.21
Vehicle Number : SMX 8006B

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 3,040.74	\$ 925.34
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 600.00	\$ 400.00 ²⁰⁰
2		To apply anti-rust		\$ 100.00	\$ 80.00
3		To putty and spray-paint of affected areas		\$ 700.00	\$ 600.00 ²⁰⁰
				\$ 1,400.00	\$ 1,080.00
					400
					(2 days)
		Sub - Total		\$ 4,440.74	\$ 2,005.34