

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI21006289/Uqf3		
3 ANSON ROAD #16-00		Date: 01/06/2021		
SPRINGLEAF TOWERS SINGAPORE 079909		Code: CTI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBH 1866X	Veh. Inspected	SME 6095G	
Policy No.	DMCVSNW00015032102	Coverage (\$)	0.00	
Claim No.	SNM21D203061/C02/TANKW	Excess (\$)	0.00	
Assign From	BILLY TAN	Assign Date	01/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/05/2021	Inspection Date	01/06/2021	
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				