



Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

*Not Authorized
L1 Sur & 2650/p
Returning After Paint*

Vehicle No : SLV 4469 Y
Make : Toyota C-HR
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	395.10
1 pc	Rear n/s tail-gate reflector	568.10
1 pc	Rear n/s tail-lamp assy	855.10
1 pc	Rear bumper	393.20
1 pc	Rear bumper reinforcement	
1 pc	Rear n/s bumper reflector garnish	
1 pc	Rear n/s bumper reflector	
1 pc	Rear lower bumper	465.76
2 pcs	Rear bumper side retainer	
2 pcs	Rear fender arch garnish	
1 pc	Rear end panel	
1 pc	Rear end panel inner garnish	

R	\$1,339.60	X
Ln	\$550.10	✓
CU	\$683.20	✓
Bul / LCH	\$985.10	✓
Ry	\$483.20	2
nd	\$125.60	✓
CM	\$95.70	✓
CM	\$655.70	✓
n/s dir	\$75.10	4
n/s Bu	\$165.20	4
R	\$725.70	X
Ln	\$402.10	X
	\$6,526.60	
Less 25 %	\$1,631.65	
	\$4,894.95	

S Nett

15 pcs	Rear bumper clip	\$2.00
1 pc	Rear reverse sensor	

Ln	\$30.00	✓
Ln	\$200.00	X

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 500

To putty & spray paint on accident affected portion

\$800.00 400

Check and reconnect wiring

\$40.00 200

To anti-rust proofing

~ ~ \$100.00 X

Total \$6,864.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: