

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 17 Jun 2021

Preliminary Advice

Insured Vehicle No	: GBB8391J		
TP Vehicle No	: SLP155K	Accident Date	: 07/04/2021
Make	: BMW 216D	Assignment Date	: 01/06/2021
Date of Inspection	: 01/06/2021	Est. Duration of Repair	: 5
Inspection At	TEAM AUTO PRO PTE LTD - SIN MING (HQ) 160 SIN MING DRIVE #01-14 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,047.90
Revised Amount	:S\$	5,549.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,549.95

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :