



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONAS LIM GUO JIANN BLK 538 HOUGANG STREET 52 #08-86 SINGAPORE 530538 Contact No	Cust No/Name	KCV15318/JONAS LIM GUO JIANN
	Reg No/Reg Date	SMR7746L / 21/01/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0602079
	Engine No	4J11BK4228
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV15318	CRDVCH	31/05/2021/ 10:25		442 / CocoLu	11504			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1920.00
RENEW FRT FENDER LH, FRT DOOR LH, REAR DOOR LH								
E PNT98000								1650.00
SPRAY PAINT FOR FRT FENDER LH, FRT DOOR LH, REAR DOOR LH								
E PNT88000								300.00
REMOVE & INSTALL FRT DOOR TRIMS, GLASS AND OTHERS								
E PNT88000								300.00
REMOVE & INSTALL REAR DOOR TRIMS, GLASS AND OTHERS								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 54900099								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
Sundry								
M	FENDER,FR LH				1.00	622.00	00.00	622.00
M	PANEL ASSY,FR DOOR,LH				1.00	982.00	00.00	982.00
M	HINGE,FR DOOR,LWR LH				1.00	43.00	00.00	43.00
M	HINGE,FR DOOR,LWR RH				1.00	43.00	00.00	43.00
M	REGULATOR,FR DOOR WDO,LH				1.00	178.00	00.00	178.00
M	MOTOR,F/DR POWER WDO REG,L				1.00	457.00	00.00	457.00
M	BASE,F/DR OUTSIDE HDLE,LH				1.00	135.00	00.00	135.00
M	GASKET,F/DR OUTSIDE HANDLE				1.00	6.00	00.00	6.00
M	COVER,F/DR OUTS HANDLE,LH				1.00	50.00	00.00	50.00
M	HANDLE,RR DOOR OUTSIDE,LH				1.00	93.00	00.00	93.00
M	LATCH,FR DOOR,LH				1.00	322.00	00.00	322.00
M	CHECK,FR DOOR				1.00	31.00	00.00	31.00
M	PANEL ASSY,RR DOOR,LH				1.00	864.00	00.00	864.00
M	TAPE,FR DOOR SASH,LH				1.00	42.00	00.00	42.00
M	TAPE,RR DOOR SASH				1.00	42.00	00.00	42.00
M	TAPE,RR DOOR SASH				1.00	42.00	00.00	42.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONAS LIM GUO JIANN BLK 538 HOUGANG STREET 52 #08-86 SINGAPORE 530538 Contact No	Cust No/Name	KCV15318/JONAS LIM GUO JIANN
	Reg No/Reg Date	SMR7746L / 21/01/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0602079
	Engine No	4J11BK4228
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV15318	CRDVCH	31/05/2021/ 10:25		442 / CocoLu	11504		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GARNISH,FR DOOR,LH			1.00	190.00	00.00	190.00
M	GARNISH,RR DOOR,LH			1.00	164.00	00.00	164.00
M	WHEEL,DISC			1.00	974.00	00.00	974.00
Estimate							

Confirm & accepted by

	Nett	9,860.00
7% GST on	9860.00	690.20
Total Payable		10,550.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.