

Repair Estimate

Make: OPEL / ASTRA
ST 1.0 AT (LED)

No.	Qty	Part Description	Price (SGD)
<u>1</u>	1	RR BUMPER	\$ 1,474.00
<u>2</u>	10	RR BUMPER CLIPS	\$ 65.00
<u>3</u>	1	RR BUMPER TOW COVER	\$ 94.00
<u>4</u>	1	RR BUMPER SIDE RETAINER RH(inner)	\$ 154.00
<u>5</u>	1	RR BUMPER SIDE RETAINER RH(outer)	\$ 164.00
<u>6</u>	1	RR BUMPER CENTER RETAINER	\$ 160.00
<u>7</u>	1	RR BUMPER SIDE RETAINER LH(inner)	\$ 154.00
<u>8</u>	1	RR BUMPER SIDE RETAINER LH(outer)	\$ 164.00
<u>9</u>	1	RR BUMPER LOW BRACKET RH	\$ 86.00
<u>10</u>	1	RR BUMPER LOW BRACKET LH	\$ 86.00
<u>11</u>	1	RR BUMPER REINFORCEMENT	\$ 537.00
<u>12</u>	1	RR BUMPER LOW GARNISH	\$ 332.00
<u>13</u>	2	RR BUMPER REVERSE SENSOR	\$ 264 132.00
<u>14</u>	1	RR BUMPER REVERSE SENSOR RUBBER SEAL	\$ 10.00
<u>15</u>	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	\$ 390.00
<u>16</u>	1	RR BUMPER REFLECTOR RH	\$ 144.00
<u>17</u>	1	RR BUMPER REFLECTOR LH	\$ 144.00
<u>18</u>	1	RR TAILGATE	\$ 2,196.00

19	10	RR TAILGATE TRIM BOARD CLIPS	<i>the new</i>	\$ 65.00	✓
20	1	RR TAILGATE ASTRA EMBLEM	<i>2</i>	\$ 174.00	✓
21	1	RR TAILGATE ASTRA LETTERING	<i>for new</i>	\$ 150.00	✓
22	1	RR TAILGATE ECO LETTERING		\$ 130.00	✓
23	1	LETTERING	✓	\$ 120.00	✓
24	1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	<i>all in included</i>	\$ 274.00	✓
25	1	RR TAILGATE REFLECTOR RH - T/Lamp Fog	<i>3 for</i>	\$ 499.00	✓
26	1	RR TAILGATE REFLECTOR LH - T/Lamp Fog	<i>for new</i>	\$ 499.00	✓
27	1	RR TAILGATE GLASS	<i>for new</i>	\$ 682.00	✓
28	1	RR TAILGATE WEATHERSTRIP	<i>for new at</i>	\$ 190.00	✓
29	1	RR END PANEL	<i>new</i>	\$ 816.00	✓
30	1	RR END PANEL TOP GARNISH	<i>for new</i>	\$ 280.00	✓
31	10	RR END PANEL TOP GARNISH CLIPS		\$ 65.00	✓

6343
570870

Parts Total: \$ 10,430.00
Less 10%: \$ 1,043.00
Total: \$ 9,387.00

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>	
<u>Rear portion</u>			
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 2,600.00	1300
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 2,200.00	1100
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 130.00	30
4	To remove and refix reverse sensor and conduct test	\$ 130.00	50
5	To remove and refix reverse camera and conduct test	\$ 130.00	50
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 195.00	✓
7	To conduct water leakage test after repairs of vehicle	\$ 65.00	✓
8	To remove and refix rear tail gate windscreen	\$ 130.00	✓

2855

Labour Total: \$ 5,580.00

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>Rear portion</u>			
1	1	Rear number plate & Bracket <i>the new</i>	\$ 45.00

Other Total: \$ 45.00

Total: \$ 15,012.00
GST 7%: \$ 1,050.84
GRAND TOTAL: \$ 16,062.84

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Suhaimi Ong

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adrian Lj
PIP 31/05/21.

64 Days.

Supplementary: 567
total: 9130.70

LKK Auto Consultants hence notify the Reparer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and • is subject to final approval from Insurance Company Acknowledged by Reparer Signature: Date:
--

SUPPLEMENTARY
VEHICLE NO: SMA3138H

VEHICLE NO: SMA3138H

[illegible]