

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP Ching.
Veron.

LEY CHOON CONSTRUCTIONS &
ENGINEERING PTE LTD
3 SUNGEI KADUT DRIVE KRANJI
INDUSTRIAL ESTATE
SINGAPORE 729556

ESTIMATE

Repair Code : CLM16824

Date in : 01/06/2021

Vehicle Num. : GBG4658R

Model : TOYOTA DYNA 100 MANUAL 3SEATER

Chassis/Eng# : JTFNT24Y80K400053/1KD1866570

Contact : 67570900 93263232, 94675910

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>HE new</i>	1	950.30	950.30
AIRCON CONDENSER FAN COWLING ASSY <i>HE new</i>	1	1202.30	1,202.30
FRONT BUMPER <i>Best</i>	1	721.90	721.90
FRONT BUMPER LH BRACKET <i>HE new</i>	1	210.30	210.30
FRONT GRILLE <i>cracked</i>	1	595.20	595.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	77.70	77.70
FRONT GRILLE GASKET SEAL <i>HE new</i>	1	39.50	39.50
FRONT LH CORNER PANEL <i>Dented</i>	1	336.30	336.30
FRONT LH CORNER PANEL BRACKET <i>HE new</i>	1	39.80	39.80
FRONT LH CORNER PANEL VERTICAL BRACKET <i>HE new</i>	1	62.30	62.30
FRONT LH DOOR <i>Dented</i>	1	1794.20	1,794.20
FRONT LH DOOR ARCH RUBBER SEAL <i>HE new</i>	1	96.40	96.40
FRONT LH DOOR LOWER HINGES (TOP & LOWER)	2	115.00	230.00
FRONT LH DOOR VERTICAL RUBBER SEAL <i>HE new</i>	1	46.70	46.70
FRONT LH DOOR WEATHER STRIP	1	181.20	181.20
FRONT LH HEADLAMP <i>cracked</i>	1	922.70	922.70
FRONT LH HEADLAMP LOWER MOULDING <i>HE new</i>	1	26.90	26.90
FRONT LH PROTECTOR GARNISH <i>cracked</i>	1	120.10	120.10

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEY CHOON CONSTRUCTIONS &
ENGINEERING PTE LTD
3 SUNGEI KADUT DRIVE KRANJI
INDUSTRIAL ESTATE
SINGAPORE 729556

Contact : 67570900 93263232, 94675910

ESTIMATE

Repair Code : CLM16824

Date in : 01/06/2021

Vehicle Num. : GBG4658R

Model : TOYOTA DYNA 100 MANUAL 3SEATER

Chassis/Eng# : JTFNT24Y80K400053/1KD1866570

FRONT LH SIDE MIRROR ASSY	<i>Damaged</i>	1	695.20	✓	695.20
* FRONT LH STEP GARNISH	<i>not nec</i>	1	374.45	X	374.45
FRONT LH WIPER GARNISH	<i>an</i>	1	187.70	✓	187.70
FRONT PANEL	<i>Dented</i>	1	1194.30	✓	1,194.30
FRONT WINDSCREEN GLASS RUBBER	<i>new</i>	1	369.40	✓	369.40
Subtotal before discount					10,474.85
Percentage discount 25%					2,618.71
Sub-total 1					7,856.14
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	X	50.00
FRONT GRILLE CLIPS - SET	<i>new</i>	1	50.00	30	50.00
FRONT LH DOOR 3D ART WORK STICKER	<i>new</i>	1	280.00	120	280.00
FRONT LH DOOR COMPANY DETAIL STICKER	<i>new</i>	1	80.00	30	80.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	✓	50.00
FRONT LH HEADLAMP LOWER MOULDING CLIPS - SET	<i>new</i>	1	20.00	X	20.00
FRONT LH WIPER GARNISH CLIPS - SET	<i>new</i>	1	20.00	10	20.00
Subtotal before discount					550.00
Percentage discount 0%					0.00
Sub-total 2					550.00
Parts-total					8,406.14

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEY CHOON CONSTRUCTIONS &
ENGINEERING PTE LTD
3 SUNGEI KADUT DRIVE KRANJI
INDUSTRIAL ESTATE
SINGAPORE 729556

ESTIMATE

Repair Code : CLM16824

Date in : 01/06/2021

Vehicle Num. : GBG4658R

Model : TOYOTA DYNA 100 MANUAL 3SEATER

Chassis/Eng# : JTFNT24Y80K400053/1KD1866570

Contact : 67570900 93263232, 94675910

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall windscreen. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To remove, reinstall dashboard fascia, meter reading and etc. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

60
X 120.00
30 60.00
✓ 120.00
X 120.00
80 100.00
X 280.00
2070 800 1,200.00
800 1,400.00
50 ✓ 80.00

3,480.00

11,886.14

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7258.15

h/s: 5.81c

Ob Demp

5.81c