

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Auto & General Insurance (Singapore) Pte Ltd

190 Clemenceau Avenue

#03-01, Singapore Shopping Centre

Singapore 239924

Attention : Motor Claim Department

Contact : 62212111 Fax No. : 67250611

Estimate : TP21-047

Date : 31/05/2021

Vehicle Num. : GZ665L

Make/Model : Mercedes Vito

Chassis/Eng# : WDF44760323084110

Accident Date : 31/05/2021

Claim No. :

Reference :

Policy No. : SI20V15723/VCV/R05

S/N	Quantity	Particular	Unit Price	Amount SS
LIST ITEMS :				
1.	1 pc	Frt Bumper <i>Del'd</i>		1,360.00
2.	2 pcs	Frt Bumper Side Holder L/R <i>new</i>	96.00	192.00
3.	1 pc	Frt Bumper Tow Hook Cover <i>new</i>		35.00
4.	1 pc	Frt Reinforcement <i>new</i>		720.00
5.	1 pc	Mercedes Logo <i>new</i>		150.00
6.	1 pc	Frt Grille Assy <i>cut</i>		230.00
7.	2 pcs	Headlamp Assy L/R <i>LH rmbld</i>	3,545.00	7,090.00
8.	2 pcs	Headlamp Bracket L/R <i>new</i>	32.00	64.00
9.	10 pcs	Frt Bumper Clips <i>new</i>	9.00	90.00
10.	1 pc	Rear Bumper Assy <i>Del'd</i>		1,510.00
11.	10 pcs	Rear Bumper Clips <i>new</i>	9.00	90.00
12.	2 pcs	Rear Bumper Bracket L/R <i>new</i>	85.00	170.00
13.	2 pcs	Rear Bumper Reflector L/R <i>new</i>	55.00	110.00
14.	1 pc	Rear Bumper Inner Base Frame <i>new</i>		315.00
15.	1 pc	End Crossmember <i>new</i>		350.00
16.	1 pc	Rear Boot Lid <i>Del'd</i>		2,530.00
17.	2 pcs	Rear Corner bumper L/R <i>new</i>	215.00	430.00
18.	2 pcs	Rear Lamp Assy L/R <i>new</i>	805.00	1,610.00
19.	1 pc	Rear Bumper Top Rubber Pad Trim <i>Del'd</i>		150.00
20.	1 pc	Rear Boot Lid Weatherstrip <i>new</i>		251.00
21.	1 pc	Rear Boot Lid Mechanism Lock <i>new</i>		285.00
22.	1 pc	Rear Boot Lid Inner Trim Board <i>new</i>		210.00
23.	1 pc	Rear Windscreen Moulding <i>new</i>		155.00
24.	2 pcs	Rear Boot Lid Damper L/R <i>new</i>	148.00	296.00
25.	2 pcs	Rear Boot Lid Hinge L/R <i>new</i>	180.00	360.00
26.	1 pc	Rear Wiper <i>new</i>		75.00
27.	1 pc	Rear Boot Lid "Mercedes" Logo <i>new</i>		50.00
28.	1 pc	Rear Exhaust Silencer Box Assy <i>Not new</i>		820.00
List TotalSS :				19,698.00
10.00% Discount SS :				1,969.80
				17,728.20

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

Auto & General Insurance (Singapore) Pte Ltd
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
Attention : Motor Claim Department
Contact : 62212111 Fax No. : 67250611

Estimate : TP21-047

Date : 31/05/2021
Vehicle Num. : GZ665L
Make/Model : Mercedes Vito
Chassis/Eng# : WDF44760323084110
Accident Date : 31/05/2021
Claim No. :
Reference :
Policy No. : SI20V15723/VCV/R05

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	2 pcs	Front & Rear Number Plate w/Frame	45.00	90.00 <i>30</i>
2.	1 pc	70 Km Sticker		25.00 <i>15</i>
3.	1 pc	"6 Pax" Sticker		25.00 <i>15</i>
4.	1 pc	Windscreen Sealant		40.00 <i>✓</i>
5.	4 pcs	Reverse Sensor	150.00	600.00 <i>200</i>
Special Nett Total S\$:				780.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				150.00 <i>60</i>
To remove, replace rear windscreen.				250.00 <i>120</i>
To remove, replace & transfer rear boot lid components.				300.00 <i>80</i>
To remove, replace rear exhaust silencer.				180.00 <i>x</i>
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				2,600.00 <i>1000</i>
To putty and respray painting on affected area.				1,800.00 <i>1000</i>
Labour Total S\$:				5,280.00

Total S\$: 23,788.20

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 02/05/21.

07 Days

Ref: 1225080

L/S: 9.8K