



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP ALG
Xiao Tony

Page No. 1

Vehicle No. SLA2017S TOYOTA FILEDER

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)						
1	FRONT DOOR LH <i>Dented</i>			1112.60		✓
1	FRONT DOOR HANDLE LH <i>new</i>			125.60		+
1	FRONT DOOR INNER TRIM BOARD LH <i>new</i>			859.20		+
1	FRONT DOOR LOCK LH <i>new</i>			235.00		+
1	REAR DOOR LH <i>Dented</i>			985.90		✓
1	REAR DOOR HINGE UPPER LH <i>new</i>			115.40		+
1	REAR DOOR HINGE LOWER LH <i>new</i>			115.40		+
1	REAR DOOR INNER TRIM BOARD LH <i>new</i>			859.20		+
1	REAR DOOR REGULATOR MOTOR LH <i>new</i>			251.00		+
1	REAR DOOR HANDLE LH <i>new</i>			125.60		+
1	REAR DOOR INNER PANEL LH <i>new</i>			435.00		+
1	REAR DOOR LOCK LH <i>new</i>			235.00		✓
1	REAR FENDER LH <i>Dented</i>			753.20		✓
1	REAR FENDER INNER SHIELD LH <i>new</i>			211.00		+
1	REAR BUMPER <i>Dented</i>			681.30		✓
1	REAR BUMPER SIDE RETAINER LH <i>new</i>			75.60		✓
				7176.00		
		less	25%	1794.00	25%	
				5382.00		
SPECIAL NETT ITEMS						
1 SET	REAR DOOR CLIPS <i>new</i>			100.00		+
1 SET	REAR DOOR FRAME STICKER <i>new</i>			150.00		60
1 SET	REAR FENDER INNER SHIELD CLIPS <i>new</i>			80.00		+
1	REAR RIM LH <i>new</i>			550.00		400
1 SET	REAR BUMPER CLIPS <i>new</i>			80.00		30
1	FRONT DOOR STICKER <i>new</i>			100.00		60
Total Parts				6442.00		

3843.60

2882.70

550

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLA2017S TOYOTA FILEDER

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	800
3	To remove , fefix wiring system at accident damage areas and check for proper function	120.00	30
4	To perform anti-rust treatment on affected areas	120.00	60
5	To conduct wheel alignment test	150.00	80
6	To remove rear bootlid mechanism	150.00	+
	Labour Total :	3540.00	
	TOTAL (PARTS & LABOUR):	9982.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L
2/s 02/06/21.

05 Days.

Total: 5402.70

L/s: A.3K.