

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel: 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0803678M

Estimate

TP CLAIM

To : SMRT Buses Ltd
Motor Claims Dept

Date : 03 Jun 2021

Dear Sirs :

Fax : 6

RE : ESTIMATE COST FOR SCANIA P410 - XE5134D
ACCIDENT INVOLVING XE5134D & SMB1332X ON 15/12/2020

ITEMS	DESCRIPTION	QTY	PRICE
1	Front side mirror assy o/s	1pc	\$ 2,499.51 <i>car</i>
2	Front top arm bracket o/s	1pc	\$ 162.39 <i>X 111</i>
3	Front bottom arm bracket o/s	1pc	\$ 218.64 <i>X 111</i>
			\$ 2,880.54
			<i>2499.51</i>
			<i>10% - 2249.55</i>
			<i>150.</i>
	To remove & replace front damaged parts	\$	280.00
	To R & R wiring for front side mirror	\$	80.00 <i>30</i>
			<i>180</i>
Total		\$	3,240.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This is on a "Without Prejudice" basis
- No signature is required.
- Resurvey new parts, P/P
- faizli@lkkauto.com
- 2249.55
- 180
- 2429.55
- 1 day
- #

Taufik 97495749
WP 3/6/21 @ 1:30pm

o/day

Resurvey new parts, P/P

faizli@lkkauto.com

2249.55

180

2429.55 *1 day* *#*