

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63288523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : SMRT Buses Ltd
Motor Claims Dept

Date : 03 Jun 2021

Dear Sirs :

Fax : 6

RE : ESTIMATE COST FOR SCANIA P410 - XE5134D ACCIDENT INVOLVING XE5134D & SMB1332X ON 15/12/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front side mirror assy o/s	1pc	\$ 2,499.51 <i>cash</i>
2	Front top arm bracket o/s	1pc	\$ 162.39 <i>X 11</i>
3	Front bottom arm bracket o/s	1pc	\$ 218.64 <i>X 11</i>
			\$ 2,880.54

Labour Charge & Misc

To remove & replace front damaged parts \$ 280.00 *150.*

To R & R wiring for front side mirror \$ 80.00 *30*

Total

\$ 3,240.54

All prices quoted are subjected to 7% GST.
LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• This is a computer generated document. No signature is required.
• This is on a "Without Prejudice" basis
• No action(s) is allowed
• Item(s) must be resurveyed and
• Approval from Insurance Company
Repairer

Taufik 97495749
WP 3/6/21 @ 130pm
o/day

Resurvey new parts, P/P
taufik@lkkauto.com