

Estimation

Date
Vehicle SFD 3663 A
Make/Model MERCEDES E250
Chassis No. WDD2120472A632086

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET <i>b1</i> ✓	1	\$	-
2	BONNET LOGO - MERCEDES <i>nh</i> ✓	1	\$	-
3	BONNET LOCK <i>x</i>	2	\$	-
4	BONNET LOCK CATCH <i>x</i>	2	\$	-
5	BONNET HINGE L+R <i>x</i>	2	\$	-
6	BONNET DAMPER L+R <i>x</i>	2	\$	-
7	BONNET STOPPER L+R <i>x</i>	2	\$	-
8	HEADLAMP L+R <i>RH CRX</i> <i>LH X</i>	2	\$	-
9	HEADLAMP BRACKET L+R <i>RH</i> <i>LH X</i>	2	\$	-
10	FRONT GRILLE <i>cr</i> ✓	1	\$	-
11	FRONT GRILLE BASE <i>cr</i> ✓	1	\$	-
12	FRONT BUMPER <i>de</i> ✓	1	\$	-
13	FRONT BUMPER NOZZLE COVER RH <i>mis</i> ✓	1	\$	-
14	FRONT BUMPER TOW COVER RH <i>x</i>	1	\$	-
15	FRONT BUMPER FOG LAMP RH <i>cr</i> ✓	1	\$	-
16	FRONT BUMPER FOG LAMP GARNISH RH <i>x</i>	1	\$	-
17	FRONT BUMPER FOG LAMP CHROME RH <i>x</i>	1	\$	-
18	FRONT BUMPER RETAINER L+R <i>LH X</i> <i>RH</i>	2	\$	-
19	FRONT BUMPER REINFORCEMENT BAR <i>x</i>	1	\$	-
20	FRONT BUMPER SPONGE <i>cr</i> ✓	1	\$	-
21	FRONT BUMPER UNDERCOVER <i>fn</i> ✓	1	\$	-
22	FRONT FENDER RH <i>b1</i> ✓	1	\$	-
23	FRONT FENDER EMBLEM RH <i>nh</i> ✓	1	\$	-
24	FRONT FENDER SIDE CHROME RH <i>nh</i> ✓	1	\$	-
25	FRONT FENDER COWLING FRONT RH <i>fn</i> ✓	1	\$	-
26	FRONT FENDER COWLING REAR RH <i>x</i>	1	\$	-
27	FRONT SUPPORT PANEL <i>x</i>	1	\$	-
28	FRONT SUPPORT PANEL TOP GARNISH <i>x</i>	1	\$	-
29	FRONT ABSORBER RH <i>x</i>	1	\$	-
30	FRONT LOWER ARM RH <i>x</i>	1	\$	-
31	FRONT CONTROL ARM RH <i>x</i>	1	\$	-
32	FRONT STRAIGHT ARM RH <i>x</i>	1	\$	-
33	FRONT UPPER ARM RH <i>x</i>	1	\$	-
34	FRONT KNUCKLE RH <i>x</i>	1	\$	-
35	FRONT KNUCKLE BEARING RH <i>?</i>	1	\$	-
36	FRONT BEARING HUB RH <i>ant</i> ✓	1	\$	-
37	FRONT RIM RH <i>ant</i> ✓	1	\$	-

			Total	\$	-
			Less 10%	\$	-
			Total	\$	-

S/Nett Items					
1	FRONT BUMPER CLIPS	1	100	\$ 30 only	100.00
2	FRONT FENDER CLIPS	1	200	\$ X	200.00
3	FRONT FENDER COWLING CLIPS	1	100	\$ 20 only	100.00
4	FRONT TYRE RH	1	800	\$ X	800.00
			Total	\$	1,200.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	1400	\$ 600	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1200	\$ 750	1,200.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 130	150.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$ 30	150.00
5	TO RNR INNER TRIM AND UPOLSTERY	1	800	\$ X	800.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$ 80	250.00
7	TO RNR UNDERCARRIAGE	1	300	\$ 150	300.00
8	TO CHECK WHEEL BALANCING	1	250	\$ 30	250.00
9	TO CHECK WATER LEAK	1	150	\$ X	150.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	1000	\$ X	1,000.00
11	TO PERFORM RUST PROOFING	1	400	\$ 30	400.00

Total Labour	\$	6,050.00
Parts Replacement Amount	\$	1,200.00
Total Amount	\$	7,250.00

Tanpik 97495749
 WP 2/6/21 @ 5pm
 L/S Resurvey after repair
 Tanpik @ Khanduwan
 \$ 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimation

Date
Vehicle SFD 3663 A
Make/Model MERCEDES E250
Chassis No. WDD2120472A632086

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	HEADLAMP NOZZLE RH <i>one photo</i>	1	\$	-
2	FRONT BUMPER INNER BRACKET RH <i>de</i>	1	\$	-
			Total	
			Less 10%	
			Total	