

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0461/2021/GW
DATE : 29-May-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

12 days exclude 2 Sundays

Johnny Boo 28 Jul 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : USAE PTE LTD
ADDRESS : 48 TOH GUAN EAST
#03-125
SINGAPORE 608586
TELEPHONE : HP +65 96336580
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900170971-01
VEHICLE NO : **SMP 5675 G**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 087556
CHASSIS NO : WAUZZZF50KA076963
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Sep-20
PLACE OF ACCIDENT : 48 TOH GUAN RD EAST #97

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5675 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	\$	360.00
2	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	300.00	\$	300.00
3	TO INSTALL SOLAR FILM FOR RHS REAR 1/4 GLASS.	S/N \$	400.00	\$	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$	200.00	\$	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	\$	1,400.00	\$	1,400.00
TOTAL LABOUR CHARGES		:	\$ 2,660.00	\$	<u>2,610.00</u>

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5675 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 2,610.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$ 1,400.00
7	TO DISMANTLE AND RENEW REAR BUMPER, TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$ 3,000.00
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$	5,300.00	\$ 2,475.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	15,952.00	\$ 9,677.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5675 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,504.00	2003.2	
2	REAR BUMPER FIXING PARTS	1	\$ 165.00		
3	REAR BUMPER SECURING STRIP	1	\$ 223.00		
4	REAR BUMPER CHROME MOULDING	1	\$ 1,016.00		
5	REAR LIGHT REFLECTOR RH	1	\$ 41.00		
6	REAR BUMPER GUIDE SECTION LH/RH- UPPER	2	\$ 46.00		
7	REAR BUMPER GUIDE SECTION RH	1	\$ 44.00		
8	REAR FENDER RH	1	\$ 3,791.00	\$	3,032.80
9	REAR SIDE WINDOW RH	1	\$ 717.00	\$	573.20
10	PRIMER	1	\$ 20.00	\$	15.76
11	REAR WHEEL HOUSING LINER RH	1	\$ 275.00		
12	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 169.00		
13	SILL PANEL TRIM ATTACHMENT PARTS	1	\$ 130.00		
14	SILL PANEL TRIM ADHESIVE TAPE	1	\$ 212.00		
15	1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
16	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
17	CAVITY WAX	S/N	\$ 140.00	\$	140.00
18	STONE CHIP	S/N	\$ 180.00	\$	180.00
19	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
20	SUNDRIES		\$ 350.00	\$	8.64
TOTAL SPARE PARTS		:	\$ 10,583.00	\$	6,513.60
TOTAL LABOUR CHARGES		:	\$ 15,952.00	\$	9,677.00
GRAND TOTAL		:	\$ 26,535.00	\$	16,190.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-22/07.21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT