

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 03 Jun 2021

**Preliminary Advice**

Vehicle No	: SMP5675G	Accident Date	: 21/09/2020
Make	: AUDI A5	Policy No.	: 1900170971
Assignment Date	: 02/06/2021	Excess	: S\$0.00
Date of Inspection	: 01/06/2021	Est. Duration of Repair	: 12
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,535.00
Revised Amount	:S\$	17,589.00
Check Items (Estimated)	:S\$	1,005.00
Total	:S\$	18,594.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	66,517.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,483.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PLEASE TAKE NOTE THAT THE ACCIDENT HAPPENED ON 21/09/2020.