

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21006313/Avf3n2
190 CLEMENCEA	J AVENUE #03-01	[Date:	23/08/2021
		(Code:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 3775L	Veh. Inspected		SMQ 6420M
Policy No.		Coverage (\$)		0.00
Claim No.	C10010400/JM	Excess (\$)		0.00
Assign From	IVY RATILLA	Assign Date		01/06/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c		1496
Engine No.	HIDDEN	Year of Reg.		2019
Chassis No.	NHP1707191563	Colour		WHITE
Odometer	60576 KM	Steering		IN ORDER
Brakes	IN ORDER	Modification		SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make		Balance
R/H Front Tyre	195/60 R15	WEST LAKE		6 mm
L/H Front Tyre	195/60 R15	WEST LAKE		6 mm
R/H Rear Tyre	195/60 R15	WEST LAKE		6 mm
L/H Rear Tyre	195/60 R15	WEST LAKE		6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2021	Inspection Date		02/06/2021
Survey held at	8 KAKI BUKIT AVE 4 #05-25 SINGAPORE 415875.			
Repairer	HUA HONG PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSTIME SEE D Accident Date Survey held at Repairer	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars Insured Veh. SMG 3775L Policy No. Claim No. C10010400/JM Assign From IVY RATILLA Vehicle Particulars Make & Model TOYOTA SIENTA Engine No. HIDDEN Chassis No. NHP1707191563 Odometer 60576 KM Brakes IN ORDER General GOOD Condition Size R/H Front Tyre 195/60 R15 L/H Rear Tyre 195/60 R15 L/H Rear Tyre 195/60 R15 L/H Rear Tyre 195/60 R15 THE VEHICLE SUSTAINED DAMAGES AT THE READAMAGES SEE DETAILS. General Accident Date 30/05/2021 Survey held at 8 KAKI BUKIT AVE 4 #05-25 SIN Repairer HUA HONG PTE LTD Re A)THE INSPECTION WAS CONDUCTED ON A"WIT B)IN ACCORDANCE TO YOUR INSTRUCTIONS, W	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars:-THIRD PARTY Insured Veh. SMG 3775L Veh. Inspected Policy No. Coverage (\$) Claim No. C10010400/JM Excess (\$) Assign From IVY RATILLA Assign Date Vehicle Particulars & Condition Make & Model TOYOTA SIENTA C.c Engine No. HIDDEN Year of Reg. Chassis No. NHP1707191563 Colour Odometer 60576 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 195/60 R15 WEST LAKE L/H Front Tyre 195/60 R15 WEST LAKE L/H Rear Tyre 195/60 R15 WEST LAKE Repairer HUA HONG PTE LTD Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTH	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Code: Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SMG 3775L Veh. Inspected Policy No. Coverage (\$) Claim No. C10010400/JM Excess (\$) Assign From IVY RATILLA Assign Date Vehicle Particulars & Condition Make & Model TOYOTA SIENTA c.c Engine No. HIDDEN Year of Reg. Chassis No. NHP1707191563 Colour Odometer 60576 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 195/60 R15 WEST LAKE L/H Front Tyre 195/60 R15 WEST LAKE L/H Rear Tyre 195/60 R15 WEST LAKE Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information Accident Date 30/05/2021 Inspection Date Survey held at 8 KAKI BUKIT AVE 4 #05-25 SINGAPORE 415875. Repairer HUA HONG PTE LTD Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISE

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: