



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

02 June 2021

QUOT202106-000002
HHTPCLAIMS21-41

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
190 CLEMENCEAU AVE
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

Attn: Motor Claims Department

Veron

ACCIDENT INVOLVING SMQ6420M, SMG3775L & SGR7316R ON 30/05/2021 ALONG GEYLANG EAST AVE 1 AT ABOUT 2200 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMQ6420M
Vehicle Make : TOYOTA
Vehicle Model : SIENTA HYBRID 7-SEATER 1.5X CVT
Vehicle Chassis No. : NHP1707191563
Policy No. : 5109921641-02-000306
Date of Accident : 30/05/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper <i>Deband</i>		\$ 684.50 ✓
2	10	Rear Bumper Clips <i>new</i>	\$ 2.50	\$ 25.00 ✓
3	1	Rear Bumper Extension (Center) <i>Deband</i>	207	\$ 423.60 ✓
4	2	Rear Bumper Sensor Garnish (LH/RH) <i>LH cut</i>	\$ 45.20	\$ 90.40 <i>45.20</i>
5	1	Rear Tailgate <i>Distorted</i>	1180	\$ 1,629.90 ✓
6	1	Rear Tailgate Lock <i>Damaged</i>	280	\$ 672.50 ✓
7	1	Rear Tailgate Garnish <i>new</i>		\$ 338.30 <i>+</i>
8	1	Rear Tailgate Weather Strip <i>new</i>		\$ 535.50 <i>+</i>
9	1	Rear Tailgate Emblem <i>new</i>		\$ 88.70 ✓
10	1	Rear Tailgate Logo (Hybrid) <i>new</i>		\$ 82.40 ✓
11	1	Rear Tailgate Trimboard <i>new</i>		\$ 260.50 <i>+</i>
12	1	Rear Windscreen Moulding <i>new</i>		\$ 225.20 ✓
13	1	Rear End Panel <i>Repis</i>		\$ 912.30 <i>+</i>
14	1	Rear End Panel (Top) <i>Repis</i>		\$ 567.20 <i>+</i>
15	1	Rear End Panel Top Garnish <i>Deband</i>		\$ 273.60 ✓
16	1	Rear Key Antenna <i>new</i>		\$ 174.60 <i>+</i>
				\$ 6,984.20
				Less 20%
				\$ 1,396.84
				\$ 5,587.36
17	1	Rear No. Plate <i>best</i>	NETT	\$ 35.00 ✓
18	1	Sealant <i>new</i>	NETT	\$ 60.00 ✓
19	1	Rear Reverse Sensor <i>Damaged</i>	NETT	\$ 200.00 ✓

3091.60

Less 25% : 2318.70

\$ 800.00 *BUD*

To dismantle, cut & weld rear end panel. To change rear bumper, rear tailgate.
To knock all area affected by accident

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

02 June 2021

QUOT202106-000002
HHTPCLAIMS21-41

ACCIDENT INVOLVING SMQ6420M, SMG3775L & SGR7316R ON 30/05/2021 ALONG GEY LANE EAST AVE 1 AT ABOUT 2200 HOURS

Estimate Repair List for vehicle SMQ6420M - TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To perform wire checking		\$ 50.00 ³⁰
		To transfer rear tailgate mechanism to new tailgate	1430	\$ 80.00 ✓
		To remove & refit rear windscreen		\$ 120.00 ✓
		To spray rear end panel, rear bumper, rear tailgate		\$ 800.00 ⁶⁰⁰
				\$ 7,732.36
				7% GST \$ 541.27
				Total \$ 8,273.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
P/P ~~HS~~ 02/06/21.
06 Days.

Toler: 4043.70
(P/P)

Authorised by Claims Dept