

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLA 5386G

Vehicle Model : NISSAN SYLPHY

Accident Date : 23.05.2021

Original Reg Date : 02.03.2016

Date : 02.06.2021

Chassis : MNTBBAB17Z0026657

TP Ins. **ERGO**

ESTIMATE

1	1 pc	Front Bumper <i>de</i>		687	N
2	1 pc	Front Bumper Reinforcement <i>bt</i>		536	N
3	1 set	Front Bumper Sponge <i>one</i>		246.50	N
4	2 pcs	Front Bumper Side Retainer <i>LH x RH RH RH</i>	<i>137 each</i>	74	N
5	1 pc	Front Bumper Clip <i>rel</i>		40	N 30
6	1 pcs	Front Bumper Fog Lamp Cover <i>RH. out</i>		125	N
7	1 pc	Head Lamp RH <i>out</i>		895	N
8	1 pc	Head Lamp Bottom Retainer RH <i>rel</i>		69	N
9	1 pc	Front Fender RH <i>rel</i>		556	N
10	1 pc	Front Fender Inner Shield RH <i>rel</i>		119	N
11	1 set	Front Fender Inner Shield Clip RH <i>rel</i>		30	N
12	1 pc	Wiper Tank <i>rel</i>		135	N

Special Nett

1	1 pc	Front Sport Rim RH <i>out</i>		500.00	
---	------	-------------------------------	--	--------	--

Labour charge

Panel Beating	450.	800.00
Spray painting	450.	800.00
Check Wiring	30.	30.00
Anti rust	30.	50.00
To perform Computerize wheel alignment.	80.	90.00

Tanpin 97495745
WP' 26/7/21 04pm
c/s Resurvey after repair
4 days
for 11 months

2618.55

500

1040

4158.55

4/3300

4 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: