

ESTIMATE FOR SGF7772U

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

027 787 Mountain Gr/ 043 381 ARTICO Mari

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

WIP No	50265
Reg No/Reg Date	SGF7772U / 26/12/2018
Date In/Mileage	
Chassis No	WDC1569422J5782583
Engine No	27091031800717
Make/Model	MB/MB GLA 180 Urban

Vehicle & Document Information

Account No	Terms -	Date/Time Printed	d CSE	Operator			144	
WI000576	Credit	01/06/2021/ 16	5:04 VS	356 / Vincent Seah	•			
	11214	Description of	of Goods / Services		Qty	Unit Price	Disc%	Amount
■ DRIVE I	NO/ACC DATE N/EXCESS /DATE SURVE	: 1800152279-02 : 01.06.2021	31.05.202 // TP CAR NO.:	SEM4990E=INDIA INS		XII		OICE
	RIZED ON	:				est		
M BPNSUN	•	•			ARTICLE AND ADDRESS OF THE PARTY OF THE PART			15.00
SUNDRIE	S			ental de la companya	コハレ	Market Ma		
A BPILAB	UTDV TO OU	-01/ 001/7001 111/77		v 70	1 / (0.10	380.00
	NIRY TO CHE D SETTINGS.	CK CONTROL UNIT	2 % KEZET MEMOR	Y 10		AND COMPANY OF THE PARTY OF THE		
A BPILAB	D SETTINGS.	METI		\sim \sim \sim \sim	1) "			120.00
	& REPLACE H	HEADLAMP WITH FO	CUS ADJUSTMENT.	NETY () ()	· ·			120.00
A RPILAR			· American Company	(2400.00
	& REPLACE (ON FRONT BUMPER,	LHF HEADLIGHT,	L'HP FÉNDER				
A BPIRES				1117				1800.00
		BUMPER, LHF FEND	ER \ \ \		1 00	1200 70	00 00	1200 70
M FRONT B			<u>`</u>		1.00 1.00	1388.72 174.94		1388.72 174.94
	TOWING EYE ABSORBER	1			1.00	174.94		174.94 155.41
M SPRING		11			4.00		00.00	14.08
	NT BUMPER.	STI VER			1.00	877.71		877.71
	WER COVER	O1E TER			1.00	305.06		305.06
	BUMPER LO	VER GRILLE			1.00	137.09		137.09
	AMP COVER				1.00		00.00	61.92
M LEFT FO	GLAMP BRACI	KET BUMPER			1.00	64.15	00.00	64.15
M COMPANY	SIGN				1.00	65.69	00.00	65.69
M GROMMET					2.00	2.64	00.00	5.28
M LEFT FR	ONT BUMPE	R MOULDING			1.00	140.45	00.00	140.45
M LEFT FR	ONT FENDER				1.00	883.64	00.00	883.64
	ERMEDIATE I				1.00		00.00	9.49
	T FENDER L				1.00	186.10		186.10
	FENDER MOUI				1.00	218.89		218.89
M FRONT S	UPPORT CAI	RRIER			1.00	677.13	00.00	677.13
Confirmed	& accepted by							

Colour/Trim

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the rubber seal or other repair requiring

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





ESTIMATE FOR SGF7772U

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT **64 CECIL STREET** #04/#05 IOB BUILDING SINGAPORE 049711 63476100

WIP No 50265 / 26/12/2018 Reg No/Reg Date SGF7772U

Vehicle & Document Information

Date In/Mileage Chassis No WDC1569422J5782583

27091031800717 Engine No MB/MB GLA 180 Urban Make/Model

027 787 Mountain Gr/ 043 381 ARTICO Mari Colour/Trim

Account No Terms Date/Time Printed CSE Operator WI000576 01/06/2021/ 16:04 ٧S 356 / Vincent Seah Credit Description of Goods / Services Qty Unit Price Disc% Amount

1.00 2581 LEFT HEADLAMP UNIT 2581 00.00 32 ′03**.** LIGHT RANGE CONTROL



Confirmed & accepted by

Nett

13,365.21

7% GST on 13365.21

935.56

Total Payable

14,300.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

