



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGF7772U

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 50265
Reg No/Reg Date SGF7772U / 26/12/2018
Date In/Mileage / 0
Chassis No WDC1569422J5782583
Engine No 27091031800717
Make/Model MB/MB GLA 180 Urban
Colour/Trim 027 787 Mountain Gr/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator
W1000576	Credit	09/06/2021/ 15:13	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

<p>M BPNSUN POLICE NO/ACC DATE : 180015229/02 15.2021 DRIVE IN/EXCESS : 01106/2021 // CAR NO SEM4990E-INDIA INS DATE IN/DATE SURVEY: 09.06.2021 // 09.06.2021 LKK DIRECT SETTLEMENT: GABRIEL WEE-INDIA INS</p>				
M BPNSUN SUNDRIES				15.00 /
A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	380.00 /
A BPILAB REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00 /
A BPILAB REMOVE & REPLACE ON FRONT BUMPER, LHF HEADLIGHT, LHF FENDER	960 X 1			2400.00
A BPIRES RESPRAY ON FRONT BUMPER, LHF FENDER	600 X 1			1800.00
M FRONT BUMPER	1.00	1388.72	00.00	1388.72
M COVER, TOWING EYE	1.00	174.94	00.00	174.94
M IMPACT ABSORBER	1.00	155.41	00.00	155.41
M SPRING NUT	4.00	3.52	00.00	14.08
M CTR FRONT BUMPER-SILVER	1.00	877.71	00.00	877.71
M ENG. LOWER COVER	1.00	305.06	00.00	305.06
M CTR FRT BUMPER LOWER GRILLE	1.00	137.09	00.00	137.09
M LH FOGLAMP COVER	1.00	61.92	00.00	61.92
M LEFT FOGLAMP BRACKET BUMPER	1.00	64.15	00.00	64.15
M COMPANY SIGN	1.00	65.69	00.00	65.69
M GROMMET	2.00	2.64	00.00	5.28
M LEFT FRONT BUMPER MOULDING	1.00	140.45	00.00	140.45
M LEFT FRONT FENDER	1.00	883.64	00.00	883.64
M LHF INTERMEDIATE LAYER	1.00	9.49	00.00	9.49
M LEFT FRT FENDER LINEAR	1.00	186.10	00.00	186.10
M LH FRT FENDER MOULDING	1.00	218.89	00.00	218.89
M FRONT SUPPORT CARRIER	1.00	677.13	00.00	677.13

Confirmed & accepted by

Steve (LKK) W/L P/L
9/6/21, 3.00pm 3 Lys
PIP, My BL Ly

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 174400347H
GST Reg No. MB 8566111-X

ESTIMATE FOR SGF7772U

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No 50265
Reg No/Reg Date SGF7772U / 28/12/2018
Date In/Mileage 0
Chassis No WDC1569422J5782583
Engine No 27091031800717
Make/Model MB/MB GLA 180 Urban
Colour/Trim 027 787 Mountain Gr/ 043 381 ARTICO Mar

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000576	Credit	09/06/2021/ 15:13	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LEFT HEADLAMP UNIT					1.00	2581.32	00.00	2581.32
M LIGHT RANGE CONTROL UNIT					1.00	703.14	00.00	703.14

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

7% GST on **Nett 13,365.21**
935.56

Total Payable 14,300.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany