

ESTIMATE FOR SGF7772U

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Vehicle & Document Information

50265 WIP No

Reg No/Reg Date

SGF7772U / 26/12/2018

Date In/Mileage

12-10 mm my 1 WDC1569422J5782583

Chassis No Engine No

27091031800717

Make/Model

MB/MB GLA 180 Urban

Colour/Trim

027 787 Mountain Gr/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator					
WI000576	Credit	09/06/2021/ 15:13	VS	356 / Vincent	; Seah Qty	Unit Price	Disc%	-	Amount
		Description of Goods	/ Services				# 70 AF		
# DART WEET	EXCEC	:1800152279-02 : 01.06-2021 // TP	1.05.2021 CAR NO. SL	M4990E=INDIA IN	AL TA	XII	VV	U	CE
DATE IN/	DATE SURVE	Y:09.06.2021 // 09.0 GABRIEL WEE-INDIA INS	06.2021 LK S	K.	//	2			15.00
M BPNSUN SUNDRIES					EP/F	7	0.10		380.00
A BPILAB "USE XENT STANDARD	RY TO CHEC SETTINGS.N	CK CONTROL UNITS & RES	ET MEMORY T	° a P	1 11 12				120.00
A BPILAB REMOVE &	REPLACE HE	ADLAMP WITH FOCUS ADJ	USTMENT NET		~			960	2400.00
A BPILAB REMOVE &	REPLACE ON	FRONT BUMPER, LHF HEA	BLIGHT, LUA	FENDER 960	ΧŢ			609	1800.00
A BPIRES RESPRAY OF	N FRONT BUI	MPER, LHF EENDER	1 8h x	₩.	1.00 1.00	1388.72 174.94	00.00	/	1388.72 174.94
M COVER, TOW M IMPACT ABS	ING EYE				1.00 1.00 4.00	155.41			155.41 14.08
M SPRING NUT M CTR FRONT	/ nec	LVER			1.00 1.00	877.71 305.06	00.00	1	877.71 305.06
M ENG. LOWER M CTR FRT BU	COVER 🐔	/BK IMI			1.00	137.09 61.92	00.00		137.09 61.92
M LH FOGLAMP M LEFT FOGLA	MP BRACKET	BUMPER ?	8		1.00	64.15	00.00		64.15 65.69
M COMPANY SI		/ Pel / CDU			2.00	2.64	00.00		5.28 140.45
LEFT FRONT	FENDER	X N/M			1.00	883.64	00.00		883.64 9.49
LHF INTERME LEFT FRT FE	NDER LINE	AR & /LIM			1.00	186.10 218.89	00.00	/	186.10 218.89
1 LH FRT FEND 1 FRONT SUPPO					1.00	677.13	00.00		677.13
Confirmed & acc	cepted by			Steve	(LKK) W	1 p.C			

9/6/21,30pm 3 dys P/P, M BL Sy

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be menced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or required after repair work has com cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



ESTIMATE FOR SGF7772U

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

12-04-da -da -da

50265

SGF7772U / 26/12/2018

Reg No/Reg Date Date In/Mileage Chassis No

WIP No

WDC1569422J5782583

27091031800717

Engine No Make/Model Colour/Trim

Operator

MB/MB GLA 180 Urban

027 787 Mountain Gr/ 043 381 ARTICO Mari

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711

Credit

63476100

Account No

WI000576

Date/Time Printed Terms 09/06/2021/ 15:13

CSE VS

356 / Vincent Seah

Qty

Unit Price Disc% 00.00 2581.32 00.00

Amount 2581.32

M LEFT HEADLAMP UNIT LIGHT RANGE CONTROL Description of Goods / Services

1.00 1.00

703-14

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett

13,365.21

7% GST on 13365.21

935.56

Total Payable

14,300.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Fax: 6779 5383 www.mercedes-benz.com.sg



FSTIMATE FOR SGF7772U

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT **64 CECIL STREET** #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Terms Date/Time Printed

Account No

Vehicle & Document Information

WIP No 50265

/ 26/12/2018 Reg No/Reg Date SGF7772U

Date In/Mileage 09/06/2021/_13670___

WDC1569422J5782583 Chassis No

27091031800717 Engine No

MB/MB GLA 180 Urban Make/Model

027 787 Mountain Gr/ 043 381 ARTICO Mari Colour/Trim

356 / Vincent Seah WI000576 15/06/2021/ 18:29 ۷S Credit Description of Goods / Services Unit Price Disc% Amount Qty

Operator

CSE

M BPNSUN POLICY NO/ACC DATE :1800152279-02 DRIVE IN/EXCESS : 01.06.2021 TP CAR NO SLM4990E

DATE IN/DATE SURVEY:09.06.2021 // 09.06.2021 STEVE- LKK 15:10PM

DIRECT SETTLEMENT: GABRIEL WEE-INDIA INS

R LOCK Nec

3.58 00.00

17.90 /

SUPPLEMENTARY

Confirmed & accepted by

Nett

7% GST on

17.90 1.25

Total Payable

17.90

19.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg