

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0440/2021/GW
DATE : 22-May-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. CHIN SIWEI
ADDRESS : 21 GHIM MOH ROAD
#10-151
SINGAPORE 270021
TELEPHONE : HP +65 94892016
TYPE OF CLAIM : OWN POLICY CLAIMS
POLICY NO : 721000107
VEHICLE NO : **SMX 7128 P**
MODEL CODE : AUDI Q3 1.4 TFSI
MODEL YEAR : 19/12/1984
ENGINE NO : CZDC 18735
CHASSIS NO : WAUZZZF36M1044875
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Apr-21
PLACE OF ACCIDENT : ALONG CORONATION WALK

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7128 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
SUB-TOTAL LABOUR CHARGES		: \$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7128 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>scr</i>	1	\$	1,634.00	
2	REAR BUMPER FIXING PARTS <i>X</i>	1	\$	211.00	
3	REAR BUMPER SPOILER <i>scr</i>	1	\$	459.00	
4	REAR BUMPER SPOILER BRACKET <i>?</i>	1	\$	48.00	
5	REAR BUMPER COVER-CENTER <i>X</i>	1	\$	97.00	
6	REAR LIGHT REFLECTOR-LH <i>scr</i>	1	\$	41.00	
7	REAR BUMER GUIDE SECTION <i>?</i>	1	\$	63.00	
8	REAR WHEEL COVER-LH/RH <i>scr</i>	2	\$	536.00	
9	SUNDRIES <i>?</i>		\$	200.00	
TOTAL SPARE PARTS		:	\$	3,289.00	
TOTAL LABOUR CHARGES		:	\$	2,752.00	
GRAND TOTAL		:	\$	6,041.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Pass - 4p90010028*
 : *to 01/06/21 @ 1300hrs*
 : *3 days*
 : *EXCESS: TBA*
 : *Repair*
 : *Reev before print*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT