

TPSMRT.

Independent

Derive

SJM6514H.

Honda Vezel

R411209615

Rear Bumper	lt	745.30	✓
Rear Bumper Clips	new	30(SN)	✓
Rear Bumper Reflector RH.	new	151.10	X
Rear Bumper Side Holder RH	new	26.70	✓
Reverse Sensor	new	280(SN)	X
Taillamp Lower Garnish.	Debond	195.90	✓
Rear RH Fender Arc Garnish.	cut	165.80	✓
Rear RH Fender Arc Garnish Clips.		20(SN)	✓

113370

S-N: 50

906.96

Panel Beating

Body Painting.

Wiring.

To remove cruise sensor.

400	200
300	120 120
50	30
100	60

Total: 1366.96

4/5: 1.1K.

02 Days.

2464.8

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: