

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721
Phone 8263 6295 (Steven) Fax 6266 2881

United Overseas Insurance Ltd
3 Anson Road , #28-01 Springleaf
Tower Singapore 079909

Date : 02-06-21

Vehicle No : EU56U
Policy No : DHOM110137511406
Chassis No : WAUZZZ4H2ENO12384
Make/Mode : AUDI A8
DOA : 21-05-21

S/N	Qty	Description	Unit Price	Amount
1	1pc	FRONT BONNET	\$ 3,400.00	\$ 3,400.00
2	1pc	FRONT RADIATOR GRILLE	\$ 2,550.00	\$ 2,550.00
3	1pc	FRONT RADIATOR GRILLER " EMBLEM "	\$ 136.00	\$ 136.00
4	1pc	FRONT HEADLAMP LH	\$ 9,350.00	\$ 9,350.00
5	1pc	FRONT HEADLAMP BRACKET LH	\$ 236.00	\$ 236.00
6	1pc	FRONT BUMPER	\$ 2,720.00	\$ 2,720.00
7	1pc	FRONT BUMPER TOWING COVER	\$ 85.00	\$ 85.00
8	1pc	FRONT BUMPER RETANNAL LH	\$ 59.50	\$ 59.50
9	1pc	FRONT BUMPER LOWER GARNISH LH	\$ 425.00	\$ 425.00
10	1pc	FRONT BUMPER NOZZLE COVER LH	\$ 59.50	\$ 59.50
11	1pc	FRONT BUMPER NOZZLE LEVER LH	\$ 187.00	\$ 187.00
12	1pc	FRONT BUMPER NOZZLE WASHER JET LH	\$ 234.00	\$ 234.00
13	1pc	FRONT BUMPER REFORCEMENT	\$ 935.00	\$ 935.00
14	1pc	FRONT BUMPER SPONCE	\$ 119.00	\$ 119.00
15	1pc	FRONT FENDER LH	\$ 1,360.00	\$ 1,360.00
16	1pc	FRONT SUPPORT PANAL	\$ 935.00	\$ 935.00
18	1pc	FRONT KNUCKER ARM LH	\$ 1,360.00	\$ 1,360.00
19	1pc	FRONT WHEEL HUP LH	\$ 510.00	\$ 510.00
20	1pc	FRONT WHEEL BEARING LH	\$ 612.00	\$ 612.00
21	1pc	FRONT LOWER ARM LH	\$ 544.00	\$ 544.00
22	1pc	FRONT ABSORBER LH	\$ 3,910.00	\$ 3,910.00
23	1pc	FRONT TIE ROD LH	\$ 238.00	\$ 238.00
24	1pc	FRONT TIE ROD END LH	\$ 153.00	\$ 153.00
25	1pc	FRONT TORSION BAR LINK	\$ 986.00	\$ 986.00
26	1pc	FRONT DRIVER SHAFT	\$ 2,890.00	\$ 2,890.00
27	1pc	FRONT FENDER INNER SHIELD FR	\$ 238.00	\$ 238.00
28	1pc	FRONT FENDER INNER SHIELD RR	\$ 204.00	\$ 204.00
29	1pc	FRONT SENSOR LH	\$ 221.00	\$ 221.00
30	1pc	FRONT SENSOR CORNER LH	\$ 221.00	\$ 221.00
31	1pc	FRONT SENSOR WIRE HARNESS CABLE ASSY	\$ 1,125.00	\$ 1,125.00
32	1pc	FRONT INTERCOOLER PROTECTOR BAR LH	\$ 204.00	\$ 204.00
33	1pc	FRONT INTERCOOLER INNER AIR DUCT LH	\$ 238.00	\$ 238.00
Balance c/f				\$ 36,445.00

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721
Phone 8263 6295 (Steven) Fax 6266 2881

United Overseas Insurance Ltd
3 Anson Road , #28-01 Springleaf
Tower Singapore 079909

Date : 02-06-21

Vehicle No : EU56U
Policy No : DHOM110137511406
Chassis No : WAUZZZ4H2ENO12384
Make/Mode : AUDI A8
DOA : 21-05-21

	Balance b/d	\$ 36,445.00
Labour Charges		
2 To rectify front bumper sensor harness wiring system		200.00
3 To knocking remove n refix front bonnet , support panal , fender lh , front bumper		4,000.00
4 To remove & install replace radiator , cooling system & all repair , including pressure test , bleed cooling system & check leaks necessary part to facilitate		2,000.00
5 To vacuum system and refill gas		200.00
6 To check for function and aligment headlamp lh & rh		200.00
7 To respray front accident portion front bonnet , front bumper , front fender lh		3,000.00
8 To towing accident vehicle to workshop		200.00
9 To wheel aligment		120.00
Total		<u>\$ 47,165.00</u>
	7% GST	<u>3,301.55</u>
Grand Total		<u><u>\$ 50,466.55</u></u>