



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104956

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 20/08/2021  
Reference CC4/FCI21006341/Kra3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. GBK 508X  
Insured Veh. YP 9596H  
Claim No. D21001674MFCV  
Policy No. D-21097490MFCV/38  
Accident Date 31/05/2021  
Inspection Date 07/06/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 350.00        |
| <b>Subtotal</b>                | <b>350.00</b> |
| <b>GST (7%)</b>                | <b>24.50</b>  |
| <b>Grand Total</b>             | <b>374.50</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                 |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                |                                                                                                 |                 | Ref: CC4/FCI21006341/Kra3q2<br>Date: 20/08/2021<br>Code: FCI2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                 |                 |                                                               |  |
| Insured Veh.                                                                                                                           | YP 9596H                                                                                        | Veh. Inspected  | GBK 508X                                                      |  |
| Policy No.                                                                                                                             | D-21097490MFCV/38                                                                               | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | D21001674MFCV                                                                                   | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            | HENRY                                                                                           | Assign Date     | 02/06/2021                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                 |                 |                                                               |  |
| Make & Model                                                                                                                           | ISUZU NHR87                                                                                     | c.c             | 1898                                                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                          | Year of Reg.    | 2019                                                          |  |
| Chassis No.                                                                                                                            | JAANHR87EK7100274                                                                               | Colour          | WHITE                                                         |  |
| Odometer                                                                                                                               | 45569 KM                                                                                        | Steering        | IN ORDER                                                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                        | Modification    | NIL                                                           |  |
| General                                                                                                                                | GOOD                                                                                            |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                 |                 |                                                               |  |
|                                                                                                                                        | Size                                                                                            | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         | 185/75 R15                                                                                      | YOKOHAMA        | 2 mm                                                          |  |
| L/H Front Tyre                                                                                                                         | 185/75 R15                                                                                      | YOKOHAMA        | 2 mm                                                          |  |
| R/H Rear Tyre                                                                                                                          | 155 R13X8 (D)                                                                                   | YOKOHAMA        | 2/2 mm                                                        |  |
| L/H Rear Tyre                                                                                                                          | 155 R13X8 (D)                                                                                   | YOKOHAMA        | 2/2 mm                                                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                 |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                                 |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                 |                 |                                                               |  |
| Accident Date                                                                                                                          | 31/05/2021                                                                                      | Inspection Date | 07/06/2021                                                    |  |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>205 BRADDELL ROAD<br>BLK C, 3RD FLOOR<br>SINGAPORE 579701. |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                 |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                 |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                 |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                 | 3 Working Days  |                                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 508X

| Qty | Description of Parts                                                                                                                                                    | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                                                                                      |                      |                           |                   |
| 1   | LH HEADLAMP                                                                                                                                                             | CRACKED              | 306.00                    | 306.00            |
| 1   | LH FRONT CORNER PANEL                                                                                                                                                   | TO REPAIR SEE LABOUR | 208.00                    | -                 |
| 1   | LH ARM MIRROR                                                                                                                                                           | SERVICEABLE          | 63.00                     | -                 |
| 1   | LH MIRROR ARM                                                                                                                                                           | SERVICEABLE          | 268.00                    | -                 |
| 1   | LH MIRROR BASE COVER                                                                                                                                                    | MISSING              | 22.00                     | 22.00             |
| 1   | LH DOOR                                                                                                                                                                 | BENT                 | 791.00                    | 791.00            |
| 1   | LH DOOR PROTECTOR (NPA)                                                                                                                                                 | NOT NECESSARY        | -                         | -                 |
| 1   | LH DOOR WEATHERSTRIP                                                                                                                                                    | SERVICEABLE          | 159.00                    | -                 |
| 2   | LH DOOR HINGE                                                                                                                                                           | TO REPAIR SEE LABOUR | 190.00                    | -                 |
| 1   | LH DOOR CHECKER                                                                                                                                                         | SERVICEABLE          | 62.00                     | -                 |
| 1   | LH DOOR GLASS OUTER MOULDING                                                                                                                                            | SERVICEABLE          | 73.00                     | -                 |
| 1   | LH DOOR GLASS CHANNEL RUBBER                                                                                                                                            | SERVICEABLE          | 76.00                     | -                 |
| 1   | FRT LH SIGNAL LAMP                                                                                                                                                      | CRACKED              | 110.00                    | 110.00            |
| 1   | FRT LH DOOR STICKER                                                                                                                                                     | NECESSARY            | 27.00                     | 27.00             |
| 1   | FRT LH DOOR VERTICAL GARNISH                                                                                                                                            | MISSING              | 29.00                     | 29.00             |
|     | LESS 15% DISCOUNT                                                                                                                                                       |                      | -357.60                   | -192.75           |
|     |                                                                                                                                                                         |                      | 2,026.40                  | 1,092.25          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                                        |                      |                           |                   |
| 1   | LH DOOR STICKER (SN)                                                                                                                                                    | NECESSARY            | 225.00                    | 150.00            |
| 1   | COMPANY STICKER (SN)                                                                                                                                                    | NECESSARY            | 20.00                     | 20.00             |
|     |                                                                                                                                                                         |                      | 245.00                    | 170.00            |
|     | <b><u>LABOUR</u></b>                                                                                                                                                    |                      |                           |                   |
|     | TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH LH FRONT PANEL ,LH FRONT DOOR ,AND AFFECTED AREA.INCLUSIVE OF THE REPAIR OF LH FRONT CORNER PANEL AND LH DOOR HINGE . |                      | 900.00                    | 540.00            |
|     | TO PUTTY AND RESPRAY ON LH FRONT PANEL,LH FRONT BUMPER ,LH FRONT DOOR AND AFFECTED AREA.                                                                                |                      | 900.00                    | 450.00            |
|     | TO CHECK WIRING AND INSTALL .                                                                                                                                           |                      | 30.00                     | 20.00             |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                         | Description of Parts                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------|---------------|---------------------------|-------------------|
|                             | TRANSFER DOOR PARTS TO NEW DOOR .          |               | 180.00                    | 60.00             |
|                             | TO INSTALL LH DOOR ADVERTISEMENT STICKER . | NOT NECESSARY | 100.00                    | -                 |
|                             |                                            |               | 2,110.00                  | 1,070.00          |
| GRAND TOTAL                 |                                            |               | 4,381.40                  | 2,332.25          |
| RECOMMENDED COST OF REPAIRS |                                            |               |                           | 2,332.25          |

Report Ref No. CC4/FCI21006341/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBK 508X

### INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. GBK 508X**

**RE-INSPECTION**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. GBK 508X**

**RE-INSPECTION**

