



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203539

INV Date 09/06/2022

Reference CC4/LPC21006344/Ega3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. PC 8868E
Insured Veh. GZ 1342L
Claim No. 20/21/21/VC00/024612
Policy No. Z/20/VC00/107563
Accident Date 23/04/2021
Inspection Date 03/06/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21006344/Ega3q2 Date: 09/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 1342L	Veh. Inspected	PC 8868E	
Policy No.	Z/20/VC00/107563	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024612	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	02/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	KING LONG XMQ6900K	c.c	6700	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	LA6R1DSB9AB203913	Colour	MULTI COLOR	
Odometer	597761 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	DOUBLESTAR	5 mm	
L/H Front Tyre	11 R22.5	DOUBLESTAR	5 mm	
R/H Rear Tyre	11 R22.5	DOUBLESTAR	5 mm	
L/H Rear Tyre	11 R22.5	DOUBLESTAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/04/2021	Inspection Date	03/06/2021	
Survey held at	11 TUAS BAY CLOSE #06-02/06-03 WEST STAR S636996			
Repairer	ONE LINE MOTORWORKS TRADING			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 8868E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL DECORATIVE LAMP	BROKEN	300.00	300.00
1	FRONT LEFT COMBINATION HEADLIGHT	BROKEN	450.00	450.00
1	FRONT WALL EXTERIOR COVER ASSY	BROKEN	280.00	280.00
	LESS 10% DISCOUNT		-103.00	-103.00
			927.00	927.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS INCLUDING DESIGN PAINTING ON SAME (MULTI COLOR).		800.00	700.00
	TO JACK /KNOCK /STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME.		450.00	350.00
	TO REMOVE COMBINATION HEADLIGHT AND REFIT NEW.		400.00	80.00
			1,650.00	1,130.00
	GRAND TOTAL		2,577.00	2,057.00
RECOMMENDED COST OF REPAIRS				2,057.00

Report Ref No. CC4/LPC21006344/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 8868E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 8868E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

