

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006348/EGS3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0003417_01

Claimant Vehicle No : SLH4444S **Insured Vehicle No :** YN363H

Date of Loss: 22/05/2021 Nature of Claim: TP Claim No: MCV2021D0002375

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH4444S**

Make & Model: CITROEN C4 CACTUS, 1.2 PureTech 82 (A) Engine No: 10B2080351514

Reg. Date: 28/12/2015 (Man. Year: 2015) Chassis No: VF70PHMZBFE506135

Colour: Grey Odometer: 88400 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,891.00	578.00	2,313.00	80.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,120.00	3,250.00	2,870.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,011.00	3,828.00	5,183.00	57.52
+ GST 7.00/7.00% (S\$)	630.77	267.96	362.81	57.52
Nett Amount (S\$)	9,641.77	4,095.96	5,545.81	57.52
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,846.96		

INSPECTION

Date of Assignment: 02/06/2021

Date Inspected: 29/06/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2021)	
Parts:	N/A	CITROEN C4 CACTUS 1.2 PureTech 82 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH4444S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
3	1		*FRONT DOOR RH ASSY	Repair	1,252.00 FS	*- FS
4	1		*SEALING PANEL RH	Not Necessary	60.00 FS	*- FS
5	1		*ADHESIVE TAPE RH	Not Necessary	163.00 FS	*- FS
6	1		*MOULDING RH	Not Necessary	139.00 FS	*- FS
7	1		*DOOR FIXINGS	Not Necessary	197.00 FS	*- FS
8	1		*EXT VIEW MIRROR RH	Cut	215.00 FS	*215.00 FS
9	1		*FRONT WING RH	Repair	432.00 FS	*- FS
10	1		*WING MOULDING RH	Cut	155.00 FS	*155.00 FS
11	1		*BADGE	Necessary	148.00 FS	*148.00 FS
					Total Parts (\$\$)	2,891.00
						578.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RHF DOOR ,RH WINGMIRROR & RHF FENDER	New	3,040.00	1,140.00
2	RESPRAY RHF DOOR ,RHF FENDER ,RH WINGMIRROR & FRT BUMPER	New	2,200.00	1,730.00
3	REMOVE & REFIT RHF DOOR COMPONENT	New	380.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	300.00	300.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			6,120.00	3,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >