



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Larry Hoe Jun Xian		Cust No/Name / Larry Hoe Jun Xian	
Blk 305D Anchorvale Link		Reg No/Reg Date SLH44445 / 28/12/2015	
#11-23		Date In/Mileage / 0	
Singapore 544305		Chassis No VF70PHMZBFE506135	
Contact No Mobile: 83996695		Engine No 10B2080351514	
		Make/Model CIT/C4 CACTUS 1.2 PURETECH ETG SHINE	
		Colour/Trim 9P5 / 24F	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	24/05/2021/ 15:30		261 / Edwin Caina	16566

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 1 RENEW RHF DOOR, RH WINGMIRROR & RHF FENDER 760 x 15				1149 3040.00
E PNT98000 1 RESpray RHF DOOR, RHF FENDER, RH WINGMIRROR & FRT BUMPER 550 x 3 + 80				1780 2200.00
E PNT88000 REMOVE & REFIT RHF DOOR COMPONENT				380.00 X
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				80.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				300.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				120.00 X
M SUNDRY SUPPLY BODY PNL SEALANT				40 80.00
M SUNDRY Sundries				20 50.00
M FRONT DOOR RH ASSY X R	1.00	1252.00	0.00	1252.00
M SEALING PANEL RH X nn	1.00	60.00	0.00	60.00
M ADHESIVE TAPE RH X nn	1.00	163.00	0.00	163.00
M MOULDING RH X nn	1.00	139.00	0.00	139.00
M DOOR FIXINGS X nn	1.00	197.00	0.00	197.00
M EXT VIEW MIRROR RH - CUT	1.00	215.00	0.00	215.00
M FRONT WING RH X R	1.00	432.00	0.00	432.00
M WING MOULDING RH - CUT	1.00	155.00	0.00	155.00

SURVEYOR NAME: Steve CLKK
 SURVEYOR SIGNATURE: 29/6/21, 5:00pm
 DATE: WIL PL
 REMARKS: P/P

Confirm & accepted by

LYK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged panels during resurvey
- To provide a copy of this estimate to the repairer

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Parts	2,613.00
Labour	6,000.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	250.00
Total (w/o GST)	8,863.00