

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-Mail: erofia@singnet.com.sg

Name : Azeli Bin Dzulkifli

Accident Date : 25-Jul-20

Vehicle No : FBR5097U

Vehicle Model : Honda
NSS300AEstimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy <i>SVC</i>	\$ 960.00 X
1	Fork under bracket <i>11</i>	\$ 200.00 X
1	Front fender <i>CU7</i>	\$ 120.00 —
1	Front rim <i>11</i>	\$ 600.00 X
1	Front brake disc <i>11</i>	\$ 130.00 X
1	Front rim shaft <i>11</i>	\$ 80.00 X
1	Front fender rear (matt black) <i>11</i>	\$ 180.00 X
1	Front side cover - R/L/H (white) <i>CNO</i>	\$ 380.00 —
1	Front side inner cover- R/L/H (silver) <i>CNO</i>	\$ 180.00 —
1	Front lower centre cover <i>CU7</i>	\$ 245.00 —
1	Handle-bar <i>SVC</i>	\$ 160.00 X
1	Handle-bar end (1 set) <i>CU7 015</i>	\$ 76.00 —
1	Mirror (1 set) <i>CU7</i>	\$ 180.00 —
1	Brake lever <i>SCR</i>	\$ 95.00 —
1	Rear side cover - R/H <i>CU7</i>	\$ 240.00 —
1	Footstep panels <i>DIS</i>	\$ 235.00 —
1	Footstep lower panels <i>DIS</i>	\$ 220.00 —
1	Exhaust pipe assy <i>DO / BNF</i>	\$ 980.00 —
1	Exhaust protector (matt black) <i>DIS</i>	\$ 110.00 —
1	Exhaust protector (chrome) <i>DIS</i>	\$ 120.00 —
1	Exhaust end cap <i>CNO</i>	\$ 95.00 —
1	Rear handle <i>R</i>	\$ 186.00 X
1	Rear fender <i>CNO</i>	\$ 210.00 —
1	Top rear fender <i>CNO</i>	\$ 155.00 —
1	Rear taillamp <i>BND</i>	\$ 280.00 —
1	Rear number plate lamp <i>BND</i>	\$ 95.00 —
		\$ 6,512.00
	Less 10%	\$ 651.20
		\$ 5,860.80

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-Mail: erofia@singnet.com.sg

Name : Azeli Bin Dzulkifli

Accident Date : 25-Jul-20

Vehicle No : FBR5097U

Vehicle Model : Honda
NSS300A

Estimated Repair Costs

Special Net Items


1	Number plate (1 set) <i>sent Rear</i>	\$	28.00	<i>10</i>
2	Fork oils <i>11</i>	\$	40.00	<i>x</i>
2	Fork oil seals <i>11</i>	\$	96.00	<i>x</i>
1	Bearing cone (1 set) <i>11</i>	\$	115.00	<i>x</i>
		\$	115.00	

S/No. Labour

1	To provide towing service (LOD)	\$	30.00	<i>✓</i>
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	120.00	<i>x</i>
3	To provide paint work	\$ <i>11</i>	800.00	<i>x</i>
4	To provide labour	\$ <i>300</i>	500.00	
		\$	1,450.00	

Grand Total \$ 7,425.80

Singapore Dollars: Seven Thousand Four Hundred Twenty-Five and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: