

(08/11/13) wef

ASS. REC. BY: Ramu

REF:

CS/A1h21006358/R1/f3

653m

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBS 3472Cat Workshop m/s SBS TRANSITof 3,410 CHUKANH CRESSCANT

Insured:

AVG

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBS 3472CYr Regn: 2005 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo B9TL 9.4L Autoc.c 9364

Colour

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

335 398

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

4V3S4P925FA173186Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NR / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

02/05/21

D.O.I.

03/06/21

Survey held at

SBS TRANSIT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

submit \$586, 8days

red:192;25%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

Accident Repair Estimate

Accident Date: 02-May-21

Bus Registration Number: SBS 3472 C

Accident Time: 15:56HRS

Bus Type: Volvo B9TL Eu5, DD, AC, 3 Axle

Accident Report Number: E/1936/2021

Date of Survey: 03-Jun-21

3rd Party Claim against: SKD 4662 L

Section A

Parts and Material Cost				
No.	Parts or Item Description	Unit/Price	Quantity	Total Cost
1	SPRAY PAINT- GREEN;5L;SG BUS	36	\$ 1.00	\$ 36.00
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
			Total Parts & Material Cost	\$ 36.00

Section B

NO.	Assessment/Repair/Spray paint (labour Cost)		
1	CONTRACTOR LABOUR COST	\$	550.00
2	WORKSHOP ADMIN COST	\$	X 192.00
3	LIVERY/ADVERTISMENT COST	NA	
4	TOWING COST	NA	
		Total Labour Cost	\$ 742.00

Section C

Summary		
	Total Cost	\$ 778.00

SURVEYOR ACCEPTANCE

NAME:

DATE:

SIGN:

RASUL - Hp 90010068

03/06/21 @ 1520

2.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SBST VERIFICATION

Nurizman Yusoff

Technical Officer

(DID) 63754264/ (HP) 84256323 | nurizmanby@sbstransit.com.sg

Bus Engineering | Seletar Depot

3 Yio Chu Kang crescent(S786010)



A member of COMFORT LLC®

03 JUN 2021

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP



TAC - ACCIDENT REPORT VIEW

Page 1 of 2

RERPORT-ID : TAC019R
USER-ID : edsfof02

ACCIDENT REPORT

DATE : 03/05/2021 11:40:12
Page : 1 of 2

Company	SBS	District	SE	IP NUMBER	
Duty IO	ANG CHONG BOON	Report No.	E/1936/2021	Accident Date	02/05/2021
Report Date	03/05/2021	Shift Code	PM SHIFT	Accident Time	15:56
Place of Accident	PAYA LEBAR ROAD AFTER BUS STOP 81111	Road Name			
Road Name	PAYA LEBAR ROAD	Junction			
Accident Type	TRAFFIC	Final Cause			
Weather Code	CLEAR	Nature Of Accident	MINOR		
Operating Hours	START WORK	Road Surface	DRY		
Traffic Volume	HEAVY	Type Of Location	STRAIGHT ROAD		
Traffic Control	UNCONTROLLED	Traffic Flow	TWO WAYS		
Collision With	VEHICLE	Ambulance Convey	N		
Fatal	0	Type Of Collision	SIDE SWIPE - SAME DIRECTION		
Police Report	N	Serious Injury	0	Minor Injury	0
Bus Towed	N	Police Report Number		Photo Taken	Y
Urgent CBR Status	N	Sketch	Y	Mechanical Fault	N
Damage To Bus		CFMS Case	N	CFMS No	
Facts of Incident	SBS3472C - RIGHT FRONT CORNER DMG I was travelling on the left most lane along Paya Lebar road after bus stop 81111 when a car (SKD4662L) on my right lane cut into my lane. The left front body of the car side swipe the right front corner of my bus. 3P panic and reversed her car a bit. No injury. That 's all.				
Brief Particulars	NA				
Reason for Late Report					

STATEMENT READ OVER TO ME
AND I AFFIRM IT TO BE TRUE AND CORRECT

SIGNATURE OF STAFF

THAM MENG KHUAN
Safety Officer
Selat Depot

NAME AND DESIGNATION OF RECORDER

CCTV

AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K



QUOTATION

Quote To

SBS Transit Ltd

Seletar Workshop

3 Yio Chu Kang Crescent

Singapore 786010

Quotation No. Q21050676

Date 31 May 2021

Terms Net 30

Attn: Mr Nurizman

S/No	Description	ManHour	ManHour Rate	Amount
<u>Repair Accident Bus - SBS 3472C</u>				
1.	Supply 3 workers for 2 days work	11	S\$50.00	S\$550.00
-	Repair Right Side Front Corner Bumper			
-	Repair Right Side Headlamp Cover			
-	Repair Front Dome			
-	Spray Painting Right Side Front Corner Bumper			
-	Spray Painting Right Side Headlamp Cover			
-	Spray Painting Front Dome			



Remark(s) All Material To Be Supplied by SBST

Total S\$550.00

This is computer generated. No signature is required.

S/No	Description Of Stock Item	Qty Indented
1	Spay pint green LI 99002074	1
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		

Authorised By:

Name

NRIC

Designation

Signature

Indented By:

Name

NRIC

Designation

Signature



BUS ENGINEERING SE WORKSHOP

WORKORDER HISTORY

Bus Number: SBS3472C
Order #: SE2105000162

Date: 31/05/2021
OrderType: SAC1

MoNumber	BusNo	BusInDate	Fault Description	Done By
SE2104002642	SBS3472C	05/May/2021 04:18	MS-M1 Docking	Surendren Asothan
SE2104001680	SBS3472C	22/Apr/2021	AC-AS1a Docking	Loo Wooi Keong

» Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	653M
Vehicle No.:	5B53472C
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2021
Vehicle Make:	VOLVO
Vehicle Model:	B9TL 9.4L AUTO TURBO AHS
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	D9194387
Chassis No.:	VV354P925FA1731B6
Maximum Power Output:	.
Open Market Value:	\$505,887.00
Original Registration Date:	02 Nov 2015
First Registration Date:	02 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	.
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 04 Jun 2021

OK