





## Accident Repair Estimate

**Accident Date:** 02-May-21

**Bus Registration Number:** SBS 3472 C

**Accident Time:** 15:56HRS

**Bus Type:** Volvo B9TL Eu5, DD, AC, 3 Axle

**Accident Report Number:** E/1936/2021

Date of Survey: 03-Jun-21

**3rd Party Claim against:** **SKD 4662 L**

## Section A

Parts and Material Cost				
No.	Parts or Item Description	Unit/Price	Quantity	Total Cost
1	SPRAY PAINT- GREEN;5L;SG BUS	36	\$ 1.00	\$ 36.00
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
				\$ -
			<b>Total Parts &amp; Material Cost</b>	<b>\$ 36.00</b>

## Section B

NO.	Assessment/Repair/Spray paint (labour Cost)		
1	CONTRACTOR LABOUR COST		\$ 550.00✓
2	WORKSHOP ADMIN COST		\$ 192.00✓
3	LIVERY/ADVERTISEMENT COST		NA
4	TOWING COST		NA
		<b>Total Labour Cost</b>	<b>\$ 742.00</b>

## Section C

Summary		
	Total Cost	\$ 778.00

### SURVEYOR ACCEPTANCE

NAME:

DATE:

**SIGN:**

RASUL - Hp 90010068

03/06/21 @ 1520

2.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date:

## SBST VERIFICATION

**Nurizman Yusoff**

## Technical Officer

(DID) 63754264/ (HP) 84256323 | [nurizmanby@sbstransit.com.sg](mailto:nurizmanby@sbstransit.com.sg)

## Bus Engineering | Seletar Depot

**3 Yio Chu Kang crescent(S786010)**



A member of COMFORT LLC®

03 JUN 2021

NURIZMAN BIN YUSOFF  
TECHNICAL OFFICER  
SELETAR BUS WORKSHOP



## TAC - ACCIDENT REPORT VIEW

Page 1 of 2

RERPORT-ID : TAC019R  
USER-ID : edsfof02

## ACCIDENT REPORT

DATE : 03/05/2021 11:40:12  
Page : 1 of 2

7248 - YCI

Company	SBS	District	SE	IP NUMBER	
Duty IO	ANG CHONG BOON	Report No.	E/1936/2021	Accident Date	02/05/2021
Report Date	03/05/2021	Shift Code	PM SHIFT	Accident Time	15:56
Place of Accident	PAYA LEBAR ROAD AFTER BUS STOP 81111	Road Name			
Road Name	PAYA LEBAR ROAD	Junction			
Accident Type	TRAFFIC	Final Cause			
Weather Code	CLEAR	Nature Of Accident	MINOR		
Operating Hours	START WORK	Road Surface	DRY		
Traffic Volume	HEAVY	Type Of Location	STRAIGHT ROAD		
Traffic Control	UNCONTROLLED	Traffic Flow	TWO WAYS		
Collision With	VEHICLE	Ambulance Convey	N		
Fatal	0	Type Of Collision	SIDE SWIPE - SAME DIRECTION		
Police Report	N	Serious Injury	0	Minor Injury	0
Bus Towed	N	Police Report Number		Photo Taken	Y
Urgent CBR Status	N	Sketch	Y	Mechanical Fault	N
Damage To Bus		CFMS Case	N	CFMS No	
Facts of Incident	SBS3472C - RIGHT FRONT CORNER DMG I was travelling on the left most lane along Paya Lebar road after bus stop 81111 when a car (SKD4662L) on my right lane cut into my lane. The left front body of the car side swipe the right front corner of my bus. 3P panic and reversed her car a bit. No injury. That 's all.				
Brief Particulars	NA				
Reason for Late Report					

STATEMENT READ OVER TO ME  
AND I AFFIRM IT TO BE TRUE AND CORRECT

SIGNATURE OF STAFF

NAME AND DESIGNATION OF RECORDER

THAM MENG KHUAN  
Safety Officer  
Selat Depot

CCTV



# AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K



## QUOTATION

### Quote To

**SBS Transit Ltd**

Seletar Workshop

3 Yio Chu Kang Crescent

Singapore 786010

Quotation No. Q21050676

Date 31 May 2021

Terms Net 30

Attn: Mr Nurizman

S/No	Description	ManHour	ManHour Rate	Amount
<b><u>Repair Accident Bus - SBS 3472C</u></b>				
1.	Supply 3 workers for 2 days work	11	S\$50.00	S\$550.00
-	Repair Right Side Front Corner Bumper			
-	Repair Right Side Headlamp Cover			
-	Repair Front Dome			
-	Spray Painting Right Side Front Corner Bumper			
-	Spray Painting Right Side Headlamp Cover			
-	Spray Painting Front Dome			



**Remark(s)** All Material To Be Supplied by SBST

**Total S\$550.00**

*This is computer generated. No signature is required.*

S/No	Description Of Stock Item	Qty Indented
1	Spay pint green LI 99002074	1
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		

Authorised By:

Name

NRIC

Designation

Signature

Indented By:

Name

NRIC

Designation

Signature



## BUS ENGINEERING SE WORKSHOP

### WORKORDER HISTORY

Bus Number: SBS3472C  
Order #: SE2105000162

Date: 31/05/2021  
OrderType: SAC1

MoNumber	BusNo	BusInDate	Fault Description	Done By
SE2104002642	SBS3472C	05/May/2021 04:18	MS-M1 Docking	Surendren Asothan
SE2104001680	SBS3472C	22/Apr/2021	AC-AS1a Docking	Loo Wooi Keong



» Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	653M
Vehicle No.:	5B53472C
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2021
Vehicle Make:	VOLVO
Vehicle Model:	B9TL 9.4L AUTO TURBO AHS
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	D9194387
Chassis No.:	VV354P925FA1731B6
Maximum Power Output:	.
Open Market Value:	\$505,887.00
Original Registration Date:	02 Nov 2015
First Registration Date:	02 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	.
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 04 Jun 2021

OK