

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Toyota

Wish

Vehicle Number : SGR2849C

Quantity	Description	Repairer's Estimate	
	BACK		
1	REVERSE SENSOR	\$200 ✓	BR
1	RIGHT TAIL LIGHT BRACKET	\$120 ✗	nn
1	END PANEL GARNISH	\$230 ✗	nn
1	TAIL LAMP LOWER BRACKET	\$120 ✗	nn
1	REAR RIGHT BUMPER RETAINER (R & L)	\$180 140 ✓	BR
1	REAR RIGHT TAILLIGHT BRACKET	\$120 ✗	nn
1	REAR LEFT TAILLIGHT BRACKET	\$120 ✗	nn
1	REAR RIGHT WHEEL BEARING	\$150 ✗	nn
1	REAR LEFT WHEEL BEARING	\$150 ✗	nn
1	SPARE TYRE BOARD	\$80 ✗	nn
1	BOOTLID WEATHERSTRIP	\$287 ✓	Tn
1	BUMPER BRACKET	\$150 ✗	nn
1	REAR RIGHT ABSORBER	\$230 ✗	nn
1	REAR LEFT ABSORBER	\$230 ✗	nn
1	REAR RIGHT MUDGUARD	\$80 ✗	nn
1	REAR LEFT MUDGUARD	\$80 ✗	nn
1	LEFT BOOTLID LAMP	\$200 ✗	nn
1	RIGHT BOOTLID LAMP	\$200 ✗	nn
1	LEFT TAIL LIGHT	\$200 ✗	nn
1	RIGHT TAIL LIGHT	\$200 ✗	nn
1	BOOT LOCK	\$277 ✓	BT
1	REAR UNDERCARRIAGE	\$900 ✗	nn
1	BOOT LID	\$1,253 ✓	DD
1	BOOT LID BADGE	\$120 75 ✓	rec
1	BOOT CHROME GARNISH	\$250 ✓	BR
1	REAR BUMPER	\$524 ✓	nn
1	END PANEL	\$800 590 ✓	DD
	LABOUR & MISC		
1	Checking of wiring, lighting and resetting	\$300 30 ✓	
1	Remove and refit rear undercarriage	\$500 ✗	
1	Wheel alignment	\$100 ✗	
1	R & R GLASS	\$800 120 ✓	
1	Apply undercoating on repaired and replaced panel	\$800 ✗	

1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 800
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 600
	Total Repair Cost :	\$12,451

Steve (LKK) 4/6/21 9.30 am

W / P

5 days

L / S

Resurvey After Spray

\$2700 limit repair