



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 25 August 2020

Your Ref: CMTD2002222/AGC

Our Ref: TP-0147/08/20

Motor Claims Department
M/s. Sompo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Ms. Agnes Chan

Madam,

Inspection of 2010 Porsche Cayman S (A)
Registration No.: SKD 2211 T
Odometer Reading: 162557 km
Chassis No.: WP0ZZZ98ZAU770931

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 30-07-2020, followed by inspection of dismantled parts on 03-08-2020 and resurvey after repairs on 05-08-2020.

The following documents were received: -

- 1) Copy of survey report by M/s. Auto Performance Appraisal
- 2) 50 copies of photos depicting damages sustained by SKD 2211 T
- 3) Accident reports by driver of SKD 2211 T and rider of FBN 8789 H
- 4) 6 copies of photos showing condition of FBN 8789 H taken by reporting centre
- 5) 7 copies of after repair photos of SKD 2211 T

The vehicle sustained LH front side damages during an accident on 25-07-2020.

Repair cost submitted was \$17,800.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Front LH fender – repair	\$ -	\$ -
1pc.	Front LH side mirror assy – refitted	1,523.80	-
1pc.	LH door assy – slightly damaged/repared	3,052.40	-
1pc.	Front LH shock absorber – repainted	2,352.40	-
1pc.	Front LH lower arm – repainted	1,425.60	-

1pc.	Front LH trust arm – repainted	\$ 1,189.70	\$ -
1pc.	Front LH knuckle arm – repainted	2,576.20	-
1pc.	Front LH wheel hub & bearing – repainted	578.00	-
1pc.	Steering rack & pinion LH tie rod – repainted	352.40	-
		<u>13,050.50</u>	<u>\$ -</u>
	Less 10%	1,305.05	-
		<u>\$ 11,745.45</u>	<u>\$ -</u>

Special Nett Items:-

1set	Front bumper lower carbon fiber skirting set (c/w 1 set) – refitted	\$ 1,500.00	\$ -
2pcs.	Sports rims (front LH/rear LH) – front repainted/rear not consistent	6,000.00	-
		<u>19,245.45</u>	<u>\$ -</u>
	Total For Parts:-	\$ 19,245.45	\$ -

Labour Charges:-

To remove, jack out, straighten, panel beating, align and renew replaced parts.	\$ 800.00	\$ 500.00
To putty and respray painting on affected areas.	1,000.00	600.00
To check wirings and lightings.	30.00	30.00
To remove, refix LH door fittings.	80.00	-
To remove, refix front LH undercarriages.	220.00	-
To conduct computerize wheel alignment test.	60.00	60.00
To supplied and applied paint protection coating. – not receipt evidence	800.00	-
To supplied and applied anti rust treatment.	60.00	60.00
	<u>22,295.45</u>	<u>\$ 1,250.00</u>
	\$ 22,295.45	\$ 1,250.00
Lump-sum repairs:	\$ 17,800.00	-
Part-By-Part (labour charges only):	-	\$ 1,250.00

Estimated period of repairs: 4 working days

Pre-accident Market Value : About \$ 120,000.00
COE rebate : \$ 37,040.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



JEFFREY ONG
Motor Appraiser